



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 8982K

| Qty | Description of Parts  | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|---------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>  |               |                           |                   |
| 1   | DOOR RR LH  | DENTED        | 3,250.00                  | 3,250.00          |
| 1   | D/RUBBER LH RR  | NECESSARY     | 525.00                    | 525.00            |
| 1   | DOOR MLDG RR LH OTR   | NECESSARY     | 340.00                    | 340.00            |
| 1   | D/RUBBER RR LH OTR  | NECESSARY     | 380.00                    | 380.00            |
| 1   | W/GUIDE LH RR   | NECESSARY     | 285.00                    | 285.00            |
|     |   |               | 4,780.00                  | 4,780.00          |
|     | <b><u>SPECIAL NETT ITEMS</u></b>  |               |                           |                   |
| 1   | SUNDRIES (SN)   | NECESSARY     | 120.00                    | 20.00             |
|     |   |               | 120.00                    | 20.00             |
|     | <b><u>LABOUR</u></b>  |               |                           |                   |
|     | LABOUR TO REPLACE, REMOVE & REINSTALL RR LHS DOOR ASSY, DOOR MLDGS RR LHS, DOOR SEALS & READJUST RR LHS DOOR ASSY.  |               | 2,500.00                  | 600.00            |
|     | LABOUR TO RESPRAY REAR LHS DOOR, INNER DOOR PANEL ASSY, FRT LHS DOOR, UNDER NET PANEL, & RR FENDER ASSY.  |               | 2,000.00                  | 600.00            |
|     | LABOUR TO REMOVE AND TRANSFER REAR LHS WINDOW GLASS, DOOR LOCK ASSY, DOOR LOCK CONTROL MODULE, DOOR RUBBER SEALS, DOOR TRIM ASSY, DOOR HINGE UPPER AND DOWN & DOOR WIRING HARNESS WITH DOOR SWITCH. |               | 700.00                    | 300.00            |
|     | LABOUR TO CARRY OUT DIAGNOSTIC CHECK.   |               | 300.00                    | 150.00            |
|     | LABOUR TO CALIBRATE, RE-ADAPT RR LHS DOOR LOCK SYSTEM & REPROGRAMMING RR DOOR GLASS AND SAFETY LOCK.  |               | 350.00                    | 200.00            |
|     | LABOUR TO INSTALL RR RHS DOOR SOLAR FILM.   | NOT NECESSARY | 420.00                    | -                 |
|     |   |               | 6,270.00                  | 1,850.00          |
|     | <b>GRAND TOTAL</b>  |               | <b>11,170.00</b>          | <b>6,650.00</b>   |



|                             |  |  |          |
|-----------------------------|--|--|----------|
| RECOMMENDED COST OF REPAIRS |  |  | 6,650.00 |
|-----------------------------|--|--|----------|

Report Ref No. CS/LIP23002543/Wny3e2

MARKET VALUE: \$67,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$29,479.00=NETT VALUE: \$37,521.00

MUHAMMAD AKID BIN MOHAMED KAMAL

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.