



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: KHOR SAW THENG		Ref: CS/HSB23002545/Acy3e2 Date: 30/06/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHA 3241B	Veh. Inspected	SGZ 1313X
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S3M04KAX	Excess (\$)	0.00
Assign From	KHOR SAW THENG	Assign Date	10/03/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	MERCEDES BENZ C300	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD2050482R183790	Colour	YELLOW
Odometer	137327 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	255/35 R19	CONTINENTAL	6 mm
L/H Front Tyre	255/35 R19	CONTINENTAL	6 mm
R/H Rear Tyre	255/35 R19	CONTINENTAL	6 mm
L/H Rear Tyre	255/35 R19	CONTINENTAL	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	08/03/2023	Inspection Date	15/03/2023
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	