

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	HSBC LIFE (SINGA		Ref:	CS3/HSB23002550/Wqy3m4	
		EVARD #48-01 MARINA BAY RE TOWER 2 SINGAPORE		Date:	20/03/2023
	ATTN: ANG YVONI	NE		Code:	HSB
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 2001Z	Veh. Inspected		SLE 8995H
	Policy No.	VFX/P2419138	Coverage (\$)		0.00
	Claim No.	S3M04JYF	Excess (\$)		0.00
	Assign From	ANG YVONNE	Assign Date		10/03/2023
2. Vehicle Particulars & Condition					
	Make & Model	HONDA STREAM 1.8	c.c		1799
	Engine No.	HIDDEN	Year of Reg.		2009
	Chassis No.	JHMRN68609S200894	Colour		SILVER
	Odometer	390624 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	215/45 R17	HABILEAD		7 mm
	L/H Front Tyre	215/45 R17	HABILEAD		7 mm
	R/H Rear Tyre	215/45 R17	HABILEAD		7 mm
	L/H Rear Tyre	215/45 R17	HABILEAD		7 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information					
	Accident Date	27/02/2023	Inspect Date / -	Time	13/03/2023 (02:11 PM)
	Survey held at	KARR AUTOWORKS PTE LTD			
		BLK 8 KAKI BUKIT AVE 4 #02-24 SINGAPORE 415875			
5a.	a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,100-\$5,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				

Report Ref No. CS3/HSB23002550/Wqy3m4

Inspected By

Asst. Automotive Assessor

MUHAMMAD AKID BIN MOHAMED KAMAL

K.K.LAU CPT(RET)

REGD Auto Consultant-SAE, Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$