

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CCG/A1623002559/U93

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJP 61

at Workshop m/s 7LM

of

Insured: SKB 2158A

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$66k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

346W
Vehicle: IN / OUT

Date: Person Contacted: 21A534215

Veh No: SJP 61X

Yr Regn: 25/05/16

Type: M.Caf / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make: Toyota Corolla c.c. 1988

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 115220 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 25U600061886

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 05/03/23

Survey held at

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 17/3/23

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/3/23 4/5 @ 1600 in handover En

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

☐ S + RS ☐ SI

Photos

Others

Report Format :

Lump Sum / I.B.I.: (\$)

TOTAL

TLM Automobile Pte Ltd**1 Defu Lane 6 Singapore 539365****UEN number: 202244624K**

Messer AJ Jetting Pte Ltd

Estimate To Repair

SJP61X - Toyota Harrier 2.0 Premium AT Airbag 2WD

Chassis No : ZSU600061886

not Authorised
her
17/3/23
1/5 @ 1600

Third Party Insurer: AIG Insurance

Date of accident : 05 Mar 2023

Date: 17 Mar 2023

3 days
take the car away

S/No	Quantity	Description	Amount
LIST ITEMS			
1	1 pc	Front fender RH <i>20</i>	\$ 1,460.00
2	1 pc	Front fender inner shield RH <i>de hwi</i>	\$ 210.00
3	5 pc	Front fender inner shield clips @ \$3.50 <i>her</i>	\$ 17.50
4	1 pc	Front door RH <i>R</i>	\$ 1,650.00
5	1 pc	Front door weatherstrip RH <i>11</i>	\$ 250.00
6	1 pc	Front door sticker - black top RH <i>11</i>	\$ 108.00
			\$ 3,695.50
Less 25%			\$ 923.88
			\$ 2,771.63
LABOUR & MISC. CHARGES			
1		To check electrical lighting concerned.	\$ 80.00
2		To rust-proofing of the affected areas.	\$ 80.00
3		Panel beating, knocking and straighten the necessary portion,	\$ 600.00
4		remove and renewal of parts, adjust and realign the same.	\$ 850.00
Putty and spray painting of the affected portion.			\$ 1,610.00
Grand Total			\$ 4,381.63

P- 1442.6
252
1081.95
950
2031.95
202
1022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: