

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01 (Claims & Performance Management)  
Singapore 068897

**Our File No:** CS/AIS23002572/KVY3Q2**Date:** 03/07/2023**REFERENCE**

Insured/Claimant: COMFORTDELGRO BUS PTE LTD Policy No: SP2003452035  
Date of Loss: 09/03/2023 Nature of Claim: OD Claim No: 202332006074

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **PD778D**  
Make & Model: ZHONG TONG LCK6103G, 6.7 D (A) Engine No: HIDDEN  
Reg. Date: 22/12/2022 (Man. Year: 2022) Chassis No: LDYEC5238N0026049  
Colour: White Odometer: 0 km  
Engine Capacity: 0 cc  
Market Value/New Car Price: S\$850,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)  
Front Left Side: Michelin 9 mm Rear Left Side: Michelin 9/9 mm  
Front Right Side: Michelin 9 mm Rear Right Side: Michelin 9/9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	65,766.00	62,786.00	2,980.00	4.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,660.00	8,810.00	3,850.00	30.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>78,426.00</b>	<b>71,596.00</b>	<b>6,830.00</b>	<b>8.71</b>
<b>- Excess (S\$)</b>	<b>4,500.00</b>	<b>4,500.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>73,926.00</b>	<b>67,096.00</b>	<b>6,830.00</b>	<b>9.24</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>5,914.08</b>	<b>5,367.68</b>	<b>546.40</b>	<b>9.24</b>
<b>Nett Amount (S\$)</b>	<b>79,840.08</b>	<b>72,463.68</b>	<b>7,376.40</b>	<b>9.24</b>

**INSPECTION**

Date of Assignment: 11/03/2023  
Date Inspected: 13/03/2023 Inspected At: Connect 3 ( WOODLANDS) (HQ)  
566 Woodlands Road (Mandai Estate)  
Singapore 728697  
Estimated Period of Repair: 12.0 days

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 03 Jul 2023)	
<b>Parts:</b>	N/A	ZHONG TONG LCK6103G 6.7 D (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PD778D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN LOWER	Cracked	4,200.00 F	*4,200.00 F
2	1		*FRONT WINDSCREEN UPPER	Cracked	2,900.00 F	*2,900.00 F
3	1		*FRONT WINDSCREEN LOWER INNER SEAL	Necessary	720.00 F	*720.00 F
4	1		*FRONT WINDSCREEN UPPER INNER SEAL	Necessary	340.00 F	*340.00 F
5	2		*FRONT RH & LH HEADLAMP ASSY	Cracked	4,900.00 F	*4,900.00 F
6	2		*FRONT RH & LH HEADLAMP INNER FRAME STRUCTURE	Cracked	2,200.00 F	*2,200.00 F
7	2		*FRONT BUMPER RH & LH	Cracked	4,760.00 F	*4,760.00 F
8	2		*FRONT BUMPER INNER STRUCTURE RH & LH	Bent	2,160.00 F	*2,160.00 F
9	1		*FRONT CENTER BUMPER INNER STRUCTURE	Bent	900.00 F	*900.00 F
10	2		*FRONT BUMPER RH & LH BRACKET	Distorted	1,170.00 F	*1,170.00 F
11	2		*FRONT RH & LH WIPER COVER	Cracked	510.00 F	*510.00 F
12	2		*FRONT RH & LH WIPER BLADE	Cut	230.00 F	*230.00 F
13	1		*FRONT PANEL OUTER	Bent	4,100.00 F	*4,100.00 F
14	1		*FRONT PANEL INNER STRUCTURE	Bent	2,900.00 F	*2,900.00 F
15	1		*FRONT GRILLE	Buckled / Warped	3,400.00 F	*3,400.00 F
16	1		*FRONT GRILLE HINGE	Distorted	530.00 F	*530.00 F
17	1		*INTERIOR ROOF TRIM	Broken / Deformed	8,700.00 F	*8,700.00 F
18	1		*WIPER MOTOR	Serviceable	2,980.00 F	*- F
19	1		*FRONT INNER PANEL STRUCTURE	Bent	4,200.00 F	*4,200.00 F
20	10		*SEALANT	Necessary	400.00 F	*400.00 F
21	1		*ERP	Necessary	26.00 F	*26.00 F
22	1		*FRONT GRILLE CHROME EMBLEM	Dented	330.00 F	*330.00 F
23	1		*FRONT CENTER BUMPER	Cracked	2,700.00 F	*2,700.00 F
24	1		*AIR VENTILATION CONTROL UNIT ASSY	Dented	2,100.00 F	*2,100.00 F
25	1		*INTERIOR PANEL GLASS	Shattered	870.00 F	*870.00 F
26	1		*DRIVER UPPER OVERHEAD CASING	Cracked	3,300.00 F	*3,300.00 F
27	1		*DASHBOARD LOWER PANEL GARNISH	Cracked	4,200.00 F	*4,200.00 F
28	1		*SEALANT	Necessary	40.00 F	*40.00 F

F=Franchise part.

**Total Parts (S\$) 65,766.00 62,786.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE FRONT LOWER WINDSCREEN	New	1,200.00	1,000.00
2	LABOUR TO REMOVE FRONT UPPER WINDSCREEN	New	1,000.00	600.00
3	LABOUR TO REMOVE ROOF TRIMS ,UPHOLSTERY,SEATS ETC TO ASSIST REPAIR	New	600.00	400.00
4	LABOUR TO REMOVE & REFIT ELECTRONIC DASHBOARD	New	600.00	400.00
5	LABOUR TO CONFIGURE NEW ELECTRONIC DASHBOARD	New	300.00	300.00
6	CHECK WIRING FOR ALL AFFECTED ELECTRONICS CONNECTIONS	New	500.00	400.00
7	LABOUR CHARGES	New	5,600.00	3,850.00
8	SPRAY PAINTING	New	2,800.00	1,800.00
9	LABOUR TO REMOVE & REFIT INTERIOR PANEL GLASS	New	60.00	60.00
			<b>Gross Labour Cost (S\$)</b>	<b>12,660.00</b>
				<b>8,810.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >