

# REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Mar 2023)  
 Parts: 143 MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Ding Auto Pte Ltd/SML7608J/11/03/2023 12:51  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No. | Qty | Part No. | Particulars                         | %Disc | %Depr | Amount                  |
|-----|-----|----------|-------------------------------------|-------|-------|-------------------------|
| 1   | 1   |          | *FRONT BUMPER                       | 0.00  | 0.00  | *560.00 F, <b>DIS</b>   |
| 2   | 1   |          | *FRONT BUMPER RETAINER RH           | 0.00  | 0.00  | *35.00 F, <b>NEC</b>    |
| 3   | 1   |          | *FRONT BUMPER RETAINER LH           | 0.00  | 0.00  | *35.00 F, <b>NEC</b>    |
| 4   | 1   |          | *FRONT BUMPER REINFORCEMENT         | ✓     | 0.00  | *340.00 F, <b>BT</b>    |
| 5   | 1   |          | *FRONT BUMPER FOAM                  | X     | 0.00  | *100.00 F, <b>NS</b>    |
| 6   | 1   |          | *FRONT BUMPER LOWER GARNISH         | X     | 0.00  | *135.00 F, <b>NN</b>    |
| 7   | 1   |          | *FRONT BUMPER UPPER SUPPORT MLDG    | X     | 0.00  | *140.00 F, <b>NN</b>    |
| 8   | 1   |          | *FRONT BUMPER SIDE TRIM COVER LH    | ✓     | 0.00  | *25.00 F, <b>WIS</b>    |
| 9   | 1   |          | *BONNET                             | 0.00  | 0.00  | *720.00 F, <b>BUC</b>   |
| 10  | 1   |          | *BONNET HINGE RH                    | 0.00  | 0.00  | *40.00 F, <b>BT</b>     |
| 11  | 1   |          | *BONNET HINGE LH                    | 0.00  | 0.00  | *40.00 F, <b>BT</b>     |
| 12  | 1   |          | *BONNET LOCK                        | X     | 0.00  | *115.00 F, <b>NN</b>    |
| 13  | 1   |          | *BONNET INSULATOR                   | 0.00  | 0.00  | *165.00 F, <b>X NS</b>  |
| 14  | 1   |          | *BONNET STAND                       | 0.00  | 0.00  | *65.00 F, <b>NN</b>     |
| 15  | 1   |          | *BONNET STAND HOOK                  | 0.00  | 0.00  | *15.00 F, <b>NN</b>     |
| 16  | 1   |          | *FRONT GRILLE BASE                  | 0.00  | 0.00  | *380.00 F, <b>CRA</b>   |
| 17  | 1   |          | *FRONT GRILLE CHROME TRIM RH        | 0.00  | 0.00  | *110.00 F, <b>CRA</b>   |
| 18  | 1   |          | *FRONT GRILLE CHROME TRIM LH        | 0.00  | 0.00  | *110.00 F, <b>CRA</b>   |
| 19  | 1   |          | *FRONT LOWER GRILLE                 | X     | 0.00  | *130.00 F, <b>NN</b>    |
| 20  | 1   |          | *FRONT GRILLE CTR BRACKET           | ✓     | 0.00  | *50.00 F, <b>NN</b>     |
| 21  | 1   |          | *FRONT GRILLE UPPER GARNISH         | ✓     | 0.00  | *280.00 F, <b>NN</b>    |
| 22  | 1   |          | *FRONT GRILLE BADGE                 | 0.00  | 0.00  | *35.00 F, <b>BT</b>     |
| 23  | 1   |          | *FRONT SUPPORT PANEL CPL            | ✓     | 0.00  | *360.00 F, <b>NN</b>    |
| 24  | 1   |          | *FRONT SUPPORT PANEL UPPER GARNISH  | 0.00  | 0.00  | *125.00 F, <b>CRA</b>   |
| 25  | 1   |          | *FRONT FENDER RH                    | 0.00  | 0.00  | *220.00 F, <b>BUC</b>   |
| 26  | 1   |          | *FRONT FENDER LH                    | 0.00  | 0.00  | *220.00 F, <b>BUC</b>   |
| 27  | 1   |          | *FRONT FENDER INNER COVER RH        | 0.00  | 0.00  | *90.00 F, <b>DIS</b>    |
| 28  | 1   |          | *FRONT FENDER INNER COVER LH        | X     | 0.00  | *90.00 F, <b>NN</b>     |
| 29  | 1   |          | *HEADLAMP ASSY RH                   | ✓     | 0.00  | *1,550.00 F, <b>CRA</b> |
| 30  | 1   |          | *HEADLAMP ASSY LH                   | ✓     | 0.00  | *1,550.00 F, <b>CRA</b> |
| 31  | 1   |          | *HEADLAMP BRACKET RH                | 0.00  | 0.00  | *55.00 F, <b>NN</b>     |
| 32  | 1   |          | *HEADLAMP BRACKET LH                | 0.00  | 0.00  | *55.00 F, <b>NN</b>     |
| 33  | 1   |          | *FOG LAMP COVER WITH CHROME TRIM RH | X     | 0.00  | *75.00 F, <b>NN</b>     |
| 34  | 1   |          | *FOG LAMP COVER WITH CHROME TRIM LH | X     | 0.00  | *75.00 F, <b>NN</b>     |
| 35  | 1   |          | *RADIATOR ASSY                      | ✓     | 0.00  | *650.00 F, <b>NN</b>    |
| 36  | 1   |          | *RADIATOR AIR GUIDE RH              | X     | 0.00  | *80.00 F, <b>NN</b>     |
| 37  | 1   |          | *RADIATOR AIR GUIDE LH              | X     | 0.00  | *80.00 F, <b>NN</b>     |
| 38  | 1   |          | *RADIATOR UPPER BRACKET RH          | 0.00  | 0.00  | *50.00 F, <b>NN</b>     |
| 39  | 1   |          | *RADIATOR UPPER BRACKET LH          | 0.00  | 0.00  | *50.00 F, <b>NN</b>     |
| 40  | 1   |          | *CONDENSOR ASSY                     | ✓     | 0.00  | *600.00 F, <b>NN</b>    |
| 41  | 1   |          | *A/C SUCTION HOSE                   | X     | 0.00  | *185.00 F, <b>NN</b>    |
| 42  | 1   |          | *A/C DISCHARGE HOSE                 | X     | 0.00  | *165.00 F, <b>NN</b>    |
| 43  | 1   |          | *FAN SHROUD ASSY CPL                | ✓     | 0.00  | *780.00 F, <b>NN</b>    |
| 44  | 1   |          | *WASHER TANK                        | 0.00  | 0.00  | *130.00 F, <b>NN</b>    |
| 45  | 1   |          | *WASHER TANK PUMP                   | 0.00  | 0.00  | *180.00 F, <b>NN</b>    |
| 46  | 1   |          | *AIR FILTER UPPER HOUSING           | X     | 0.00  | *135.00 F, <b>NN</b>    |
| 47  | 1   |          | *AIR FILTER LOWER HOUSING           | X     | 0.00  | *125.00 F, <b>NN</b>    |





# Estimates on Miscellaneous Items

| No                         | Qty | Particulars                                             | Amount    |
|----------------------------|-----|---------------------------------------------------------|-----------|
| <u>Miscellaneous Items</u> |     |                                                         |           |
| 1                          | 1   | FRT CAR PLATE & FRAME                                   | 35.00     |
| 2                          | 1   | FRT GRILLE, BUMPER GARNISH, INNER COVER & PANEL - CLIPS | 50 200.00 |
| 3                          | 1   | HEADLAMP - ECU RE-PROGRAMMING/RE-SETTING                | 300.00    |
| Sub Total (S\$)            |     |                                                         | 535.00    |

35.00  
50 200.00  
300.00

## Estimates on Labour

| No                      | Particulars                                                                               | Lab. Type | Amount       |
|-------------------------|-------------------------------------------------------------------------------------------|-----------|--------------|
| <u>Labour Items</u>     |                                                                                           |           |              |
| 1                       | BODY REPAIR, PANEL BEAT & STRAIGHTEN/ALIGN - ACCIDENT AREA                                | New       | 600 1,200.00 |
| 2                       | SPRAY PAINT - FRONT BUMPER, BONNET, FRONT FENDER X2, GRILLE UPPER GARNISH & SUPPORT PANEL | New       | 300 1,200.00 |
| 3                       | REMOVE & REFIT - FRONT UNDERCARRIAGE COMPONENTS                                           | New       | 300.00       |
| 4                       | REFILL - RADIATOR COOLANT                                                                 | New       | 30 80.00     |
| 5                       | REFILL - AIR COND GAS                                                                     | New       | 50 80.00     |
| Gross Labour Cost (S\$) |                                                                                           |           | 2,860.00     |

Ding Auto Pte Ltd/SML7608/J11/03/2023 12:51. Not valid without Reference section.  
Generated using Merimen e-Claims IAS

< END OF ESTIMATES >

REPAIR 7 DAYS

- NOT AUTHORISE
- EXCESS \$2000
- P/P OR T/S REPAIR
- SURVEY BY EDWARD TEL 62563561
- RESURVEY BEFORE PAINT FOR P/P REPAIR
- Repair Limit \$10,000-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

|                               |                             |                       |                   |
|-------------------------------|-----------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (Own Damage)             | Ref. No:              |                   |
| Policy No:                    | SPMF1000000534              | Date of Loss:         | 09/03/2023        |
| Vehicle Reg. No.:             | SML7608J                    | Driveable?            |                   |
| Driver Age/Info:              | / MALE                      | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | NO                          | Third Party Involved? | YES               |
| Insured/Claimant              | BIZTEK LEASING              | Contact No:           | +6598321500       |
| Driver:                       | LIM GUANG XIAN              |                       |                   |
| Make/Model:                   | MAZDA 3, 1.5 L 4-DOOR SEDAN | Vehicle Reg. Date:    | 29/09/2014        |
|                               | SP.6EAT (A)                 |                       |                   |
| Vehicle Colour:               | Red                         |                       |                   |
| Engine No:                    | P520227730                  | Chassis No:           | JM6BM42A8F0143196 |
| Odometer:                     | 127387 KM                   |                       |                   |
| Paint Type:                   |                             |                       |                   |
| Total Loss?                   | NO                          |                       |                   |
| Est. Duration of Repair (day) | 15                          |                       |                   |
| Present Location:             | DING AUTO PTE LTD (HQ)      |                       |                   |

| COST OF CLAIMS      | Amount    |
|---------------------|-----------|
| Parts               | 14,184.50 |
| Miscellaneous Items | 535.00    |
| Labour              | 2,860.00  |
| Paintwork Labour    | 0.00      |
| Towing              | 0.00      |
| Gross Total (\$\$)  | 17,579.50 |
| + GST 8.00% (\$\$)  | 1,406.36  |
| Nett Amount (\$\$)  | 18,985.86 |

This claim is handled by: HENRY LEE YOON SANG