

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EQI23002574/TVY3M4**Date:** 31/05/2023**REFERENCE**

Handling Insurer: EQ Insurance Company Ltd

Policy No:

Claimant Vehicle No : SLP429X**Insured Vehicle No :** GBC2352G

Date of Loss: 09/03/2023

Nature of Claim: TP

Claim No: DM23HO00534

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLP429X**

Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)

Engine No: HRA2414980A

Reg. Date: 25/05/2017 (Man. Year: 2017)

Chassis No: SJNFEAJ11U1936929

Colour: Grey

Odometer: 137386 km

Engine Capacity: 1197 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R17

Rear Tyre Size: 215/60R17

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,886.50	1,710.50	176.00	9.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	570.00	330.00	240.00	42.11
Paintwork Labour	550.00	400.00	150.00	27.27
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,006.50	2,440.50	566.00	18.83
+ GST 8.00/8.00% (S\$)	240.52	195.24	45.28	18.83
Nett Amount (S\$)	3,247.02	2,635.74	611.28	18.83

INSPECTION

Date of Assignment: 13/03/2023 Present Location:

Kan Fook Sing Motor Workshop (Defu)

Date Inspected: 14/03/2023 Inspected At:

KAN FOOK SING MOTOR WORKSHOP

BLK.8 JTC DEFU INDUSTRIAL CITY

#04-29 DEFU SOUTH STREET 1

SINGAPORE 533758

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 May 2023)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP429X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH (WCP)	Cut	480.00 F	*400.00 F
2	1		*FRONT BUMPER (WCP)	Deformed	400.00 F	*400.00 F
3	1		*FRONT BUMPER SIDE RETAINER LH (WCP)	Deformed	25.00 F	*25.00 F
4	10		*FRONT BUMPER CLIP (WCP)	Necessary	25.00 F	*25.00 F
5	1		*FRONT FENDER LH (WCP)	Bent	420.00 F	*420.00 F
6	1		*FRONT FENDER SHIELD LH (WCP)	Not Necessary	90.00 F	*- F
7	10		*FRONT FENDER SHIELD CLIP (WCP)	Necessary	25.00 F	*25.00 F
8	1		*FRONT FENDER WHEEL ARCH GARNISH LH (WCP)	Cut	250.00 F	*260.00 F
F=Franchise part.						
Sub Total (\$\$)					1,715.00	1,555.00
+ Margin on L,N Items 10.00/10.00% (\$\$)					171.50	155.50
Total Parts (\$\$)					1,886.50	1,710.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	SPRAYPAINTING CHARGES	New	550.00	400.00
<u>Labour Items</u>				
2	TO CHECK WIRING SYSTEM	New	50.00	30.00
3	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	520.00	300.00
Gross Labour Cost (S\$)			1,120.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >