

(08/11/13) wef

ASS. REC. BY: PMV

REF:

CS/EG123002575/RgY3

581B

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP/WS/TP RES/OD RES/EVA/INV/MVTo Inspect Vehicle No: SMN 736Hat Workshop m/s MOVAof 15, FAN YOUNG RDInsured: EG1

Policy No.

Claims No.

Sum Insured: Excess: 500

(Client's Record)

Make of Veh:

(Policy Condition)

1:30pm

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 132K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SMN 736HYr Regn: 2019 12 JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B.M.W X1SDR 182 LEA MV c.c 1499

Colour

BLACK

A/C: Insured / Std / NI / NA

Sp. Reading

SS133

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBAJH 120303617110

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50R18

R:

1

BS/ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

08/03/23

D.O.I.

21/03/23

Survey held at

MOVA (FY)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction

REPAIR LIAISON 74K

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$))



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER:

ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPG22009767	Date of Loss:	08/03/2023
Vehicle Reg. No.:	SMN736H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN POH HUAT		
Make/Model:	BMW X1 SDRIVE18I, 1.5 LED NAV (A)	Vehicle Reg. Date:	24/07/2019
Vehicle Colour:	BLACK	Chassis No:	WBAJG120303G77710
Engine No:	38795596B38A15A		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	12,994.74
Miscellaneous Items	0.00
Labour	1,610.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	14,604.74
+ GST 8.00% (S\$)	1,168.38
Nett Amount (S\$)	15,773.12

This claim is handled by: ONG

Generated using Merlimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronized: 13 Mar 2023)
 Parts: M1-SUV BMW X1 (G01) 1.5L LED XAV (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-disconnected (Standard List))
 Print Code: (Unsubmitted, no print-code for BMW 10000)
 Validity: These estimates are valid only if they contain the valid code (shown on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page)
 Further Info: Items/values not in reference catalogue are part and whole are indicated

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET <i>lt</i>			
2	1		*FRONT BONNET EMBLEM <i>nc</i>	0.00	0.00	*2,499.90 F
3	1		*FRONT GRILLE RH <i>su</i>	0.00	0.00	*124.80 F
4	1		*FRONT BUMPER <i>de</i>	0.00	0.00	*239.60 F
5	1		*FRONT BUMPER LOWER GRILLE <i>de</i>	0.00	0.00	*1,646.40 F
6	1		*FRONT BUMPER REINFORCEMENT <i>lt</i>	0.00	0.00	*398.40 F
7	1		*FRONT BUMPER LIP <i>de</i>	0.00	0.00	*595.80 F
8	1		*FRONT BUMPER DIFFUSER <i>de</i>	0.00	0.00	*429.10 F
9	1		*FRONT BUMPER SIDE GARNISH COVER RH <i>su</i>	0.00	0.00	*396.40 F
10	1		*FRONT BUMPER SIDE GARNISH COVER MOULDING RH <i>su</i>	0.00	0.00	*242.30 F
11	1		*FRONT BUMPER DISTANCE SENSOR RH <i>su</i>	0.00	0.00	*176.40 F
12	1		*FRONT BUMPER TOWING COVER <i>de</i>	0.00	0.00	*394.15 F
13	1		*FRONT BUMPER FOG LAMP RH <i>de</i>	0.00	0.00	*96.30 F
14	1		*FRONT BUMPER REINFORCEMENT BRACKET RH <i>?</i>	0.00	0.00	*475.65 F
15	1		*FRONT HEADLAMP RH <i>ca</i>	0.00	0.00	*169.95 F
16	1		*FRONT WIPER TANK <i>?</i>	0.00	0.00	*3,655.65 F
17	1		*FRONT FENDER RH -REPAIR	0.00	0.00	*272.60 F
						-
Sub Total (\$\$)						11,813.40
+ Margin on L,N Items 10.00% (\$\$)						1,181.34
Total Parts (\$\$)						12,994.74

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

9:22 AM

Estimates on Miscellaneous Items

Estimate Report

Estimates on Labour

No Particulars

Labour Items

No	Particulars	Lab.Type	Amount
1	TO REMOVE, REPLACE & REFIT FRONT BUMPER DISTANCE SENSOR, DISTANCE SENSOR RADAR & ETC. TO EFFECT REPLACE OF FRONT BUMPER	New	80 100.00
2	TO REMOVE, REPLACE, REPAIR, REFIT & READJUST FRONT ACCIDENT AREAS SUCH AS FRONT BONNET, FRONT GRILLE, FRONT BUMPER, FRONT HEADLAMP & ETC. BACK TO ORIGINAL CONDITIONS	New	500 600.00
3	TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER RH & ETC.	New	600.00
4	TO CHECK WIRING & ELECTRICAL SYSTEM	New	30 80.00
5	TO DIAGNOSIS FAULTY CODE & RESET MEMORY	New	150 180.00
Gross Labour Cost (\$\$)			1,610.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rosul

Hy 90010068

5 days

P/P

EXCESS-TBA

Reset

Resurvey before paint

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 581B

Vehicle Details

Vehicle No.: SMN736H

Vehicle to be Exported: No

Intended Deregistration Date: 21 Mar 2023

Vehicle Make: B.M.W.

Vehicle Model: X1 SDRIVE18I LED NAV

Primary Colour: Black

Manufacturing Year: 2019

Engine No.: 38795596B38A15A

Chassis No.: WBAJG120303G77710

Maximum Power Output: 103.0 kW (138 bhp)

Open Market Value: \$36,905.00

Original Registration Date: 24 Jul 2019

First Registration Date: 24 Jul 2019

Transfer Count: 0

Actual ARF Paid: \$43,667.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 23 Jul 2029

PARF Rebate Amount: \$32,750.00

Intended COE Rebate Details

COE Expiry Date: 23 Jul 2029

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$39,406.00

COE Rebate Amount: \$24,978.00

Total Rebate Amount: \$57,728.00

BMW X1 sDrive18i

Overview

Insurance

Financial

Accessories

Similar

Research

Photos

Republic Auto



A member of the Jardine Cycle & Carriage Group

Price **\$132,800**

Depreciation **\$17,700 /yr**
View models with similar depre

Reg Date 05-Jul-2019
(6yrs 3mths 13days COE left)

Mileage 41,915 km (11.3k /yr)

Manufactured 2019

Road Tax \$684 /yr

Transmission Auto

Dereg Value \$57,136 as of today (change)

OMV \$36,318

COE \$39,728

ARF \$42,846

Engine Cap 1,499 cc

Power 103.0 kW (138 bhp)

Curb Weight 1,430 kg

No. of Owners 2