

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123002592/UWY3Q2**Date:** 19/04/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SJQ4644H **Insured Vehicle No :** XE5666K

Date of Loss: 09/03/2023 Nature of Claim: TP Claim No: CDMCG23000599

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJQ4644H**

Make & Model: KIA CERATO K3, 1.6 (A) Engine No: G4FGHH689392

Reg. Date: 03/01/2018 (Man. Year: 2017) Chassis No: KNAFX411MJ5758059

Colour: Blue Odometer: 91577 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,621.16	10,423.16	22,198.00	68.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,730.00	2,850.00	4,880.00	63.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	40,351.16	13,273.16	27,078.00	67.11
Approved Total (Overridden) (S\$)		10,500.00		
Nett Amount (S\$)	40,351.16	10,500.00	29,851.16	73.98

INSPECTION

Date of Assignment: 13/03/2023

Date Inspected: 13/03/2023 Inspected At:

1 KAKI BUKIT AVE 6
#01-73, AUTOBAY @KAKI BUKIT
SINGAPORE 417883
Repairer:SPEEDWERKZ PTE LTD (HQ)

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2023)
Parts:	143	KIA CERATO K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJQ4644H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER INNER SHIELD RH	Torn	198.50 FL	*166.00 FL
2	1		*FRONT FENDER	Dented	908.00 FL	*481.00 FL
3	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	144.60 FL	*- FL
4	1		*FRONT DOOR WING MIRROR COVER RH	Cut	235.00 FL	*142.00 FL
5	1		*FRONT DOOR WING MIRROR ASSY RH	Damaged	1,487.00 FL	*805.00 FL
6	1		*FRONT DOOR RH	Badly Dented	1,515.00 FL	*1,277.00 FL
7	1		*FRONT DOOR RUBBER RH	Torn	227.00 FL	*118.00 FL
8	1		*FRONT DOOR FRAME BLACK TAPE RH	Necessary	90.00 FL	*60.00 FL
9	1		*FRONT DOOR TOP HINGES RH	Bent	95.90 FL	*82.00 FL
10	1		*FRONT DOOR CHECKER RH	Twisted	95.90 FL	*95.90 FL
11	1		*FRONT DOOR INNER LOCK RH	Damaged	131.80 FL	*131.80 FL
12	1		*FRONT DOOR OUTER HANDLE	Cut	792.80 FL	*242.00 FL
13	1		*FRONT DOOR OUTER HANDLE BASE RH	Not Necessary	191.60 FL	*- FL
14	1		*FRONT DOOR OUTER HANDLE KNOB RH	Cut	147.00 FL	*147.00 FL
15	1		*FRONT DOOR GLASS REGULATOR MOTOR RH }	Bent / Jammed	345.50 FL	*345.50 FL
16	1		*FRONT DOOR GLASS REGULATOR RH }		101.90 FL	*- FL
17	1		*FRONT DOOR GLASS CHANNEL RH	Not Necessary	688.40 FL	*- FL
18	1		*FRONT DOOR CHANNEL BRACKET RH	Not Necessary	220.00 FL	*- FL
19	1		*FRONT DOOR BOARD RH	Deformed / Torn	912.80 FL	*601.00 FL
20	1		*FRONT DOOR GLASS OUTER MOULDING RH	Bent	227.00 FL	*82.00 FL
21	1		*FRONT DOOR PILLAR RH	Repair	655.00 FL	*- FL
22	1		*FRONT WINDSCREEN GLASS MOULDING	Not Necessary	72.60 FL	*- FL
23	1		*REAR DOOR RH	Badly Dented	1,417.50 FL	*1,377.00 FL
24	1		*REAR DOOR FRAME BLACK TAPE RH	Necessary	75.90 FL	*60.00 FL
25	1		*REAR DOOR INNER LOCK RH	Damaged	819.70 FL	*245.00 FL
26	2		*REAR DOOR BOTTOM HINGE	Bent	191.60 FL	*82.00 FL
27	1		*REAR DOOR OUTER HANDLE RH	Not Necessary	215.00 FL	*- FL
28	1		*REAR DOOR RUBBER	Torn	217.00 FL	*115.00 FL
29	1		*REAR DOOR GLASS REGULATOR MOTOR RH }	Bent / Jammed	435.00 FL	*350.00 FL
30	1		*REAR DOOR GLASS REGULATOR RH }		688.40 FL	*- FL
31	1		*REAR DOOR BOARD RH	Deformed / Torn	918.70 FL	*595.00 FL
32	1		*REAR DOOR CHECKER RH	Twisted	85.90 FL	*85.90 FL
33	1		*REAR TAIL LAMP 866 RH	Not Necessary	866.00 FL	*- FL
34	1		*REAR FENDER RH	Dented / Bent	1,172.00 FL	*1,172.00 FL
35	1		*REAR FENDER INNER GARNISH	Not Necessary	99.80 FL	*- FL
36	1		*REAR BUMPER	Repair	795.60 FL	*- FL
37	1		*REAR BUMPER REFLECTOR RH	Not Necessary	62.10 FL	*- FL
38	2		*REAR BUMPER SIDE RETAINER	Not Necessary	144.60 FL	*- FL
39	1		*FRONT ABSORBER	N/S Not Necessary / O/S Bent	787.60 FL	*313.00 FL
40	1		*FRONT LOWER ARM	N/S Not Necessary / O/S Bent	958.30 FL	*380.00 FL
41	1		*FRONT KNUCKLE ARM	N/S Not Necessary / O/S Bent	1,212.60 FL	*393.00 FL
42	2		*FRONT DRIVE SHAFT	Not Necessary	1,916.00 FL	*- FL
43	1		*FRONT ENGINE CROSS MEMBER	Not Necessary	865.00 FL	*- FL
44	1		*STEERING RACK & PINION	Not Necessary	2,422.70 FL	*- FL
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*REAR SHOCK ABSORBER	N/S Not Necessary /O/S Twisted	1,302.60 FL	*280.00 FL
46	2		*REAR KNUCKLE ARM	No such part	1,902.40 FL	*- FL
47	1		*REAR WHEEL BEARING WITH HUB	N/S Not Necessary / O/SDamaged	902.40 FL	*390.00 FL
48	2		*REAR LOWER ARM	No such part	1,790.40 FL	*- FL
49	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	78.30 FL	*78.30 FL
50	2		*FRONT AND REAR TYRE RH	Serviceable	900.00 FS	*- FS
51	2		*FRONT AND REAR SPORT RIMS RH	Bent / Warped	3,000.00 FS	*800.00 FS
52	6		*REAR FENDER INNER GARNISH CLIPS	Not Necessary	77.40 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	35,803.80	11,492.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,182.64	1,069.24
Total Parts (\$\$)	32,621.16	10,423.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	150.00	20.00
2	APPLY ANTI RUST	New	200.00	100.00
3	REMOVE & REFIX CUSHION UPHOLSTERY	New	350.00	80.00
4	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	150.00	120.00
5	REMOVE AND REFIX FRONT & REAR UNDER CARRIAGE ,SUSPENSION SYSTEM	New	800.00	250.00
6	CHECK WHEEL ALIGNMENT	New	120.00	80.00
7	REMOVE AND REFIX REVERSE SENSOR	New	160.00	0.00
8	LABOUR FOR PANEL BEATING & REPLACE PARTS	New	3,000.00	1,000.00
9	TO SPRAY PAINTING	New	2,800.00	1,200.00
Gross Labour Cost (S\$)			7,730.00	2,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >