

Vehicle Damage Assessment Report for [SJQ4644H]

Estimate Created: 12/04/2023 16:18 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 12/04/2023 16:35 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Kia	Model	Cerato
Engine Type			
License Plate Number	SJQ4644H	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$10,500.00 WITH 6 WORKING DAYS

Insurlogic 4 (12/04/2023 16:35)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
RH front fender inner shield		1	166.00	-10.00 %	149.40
RH front fender		1	481.00	-10.00 %	432.90
RH front door wing mirror cover		1	142.00	-10.00 %	127.80
RH front door wing mirror assy		1	805.00	-10.00 %	724.50
RH front door		1	1277.00	-10.00 %	1,149.30
RH front door rubber		1	118.00	-10.00 %	106.20
RH front door frame black tape		1	60.00	-10.00 %	54.00
RH front door top hinge		1	82.00	-10.00 %	73.80
RH front door checker		1	95.90	-10.00 %	86.31
RH front door inner lock		1	131.80	-10.00 %	118.62
RH front door outer handle		1	242.00	-10.00 %	217.80
RH front door outer handle knob		1	147.00	-10.00 %	132.30
RH front door glass regulator with motor		1	345.50	-10.00 %	310.95
RH front door board		1	601.00	-10.00 %	540.90
RH front door glass outer moulding		1	82.00	-10.00 %	73.80
RH rear door		1	1377.00	-10.00 %	1,239.30
RH rear door frame black tape		1	60.00	-10.00 %	54.00
RH rear door inner lock		1	245.00	-10.00 %	220.50
RH rear door bottom hinge		1	82.00	-10.00 %	73.80
RH rear door rubber		1	115.00	-10.00 %	103.50
RH rear door glass regulator with motor		1	350.00	-10.00 %	315.00
RH rear door board		1	595.00	-10.00 %	535.50
RH rear door checker		1	85.90	-10.00 %	77.31
RH rear fender		1	1172.00	-10.00 %	1,054.80
RH front shock absorber		1	313.00	-10.00 %	281.70
RH front lower arm		1	380.00	-10.00 %	342.00
RH front knuckle arm		1	393.00	-10.00 %	353.70
RH rear shock absorber		1	280.00	-10.00 %	252.00
RH rear wheel bearing with hub		1	390.00	-10.00 %	351.00
Rear windscreen glass moulding		1	78.30	-10.00 %	70.47

Parts Subtotal 9,623.16

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
RH front and rear sport wheel rim		2.0	400.00	0.00 %	800.00
Materials Subtotal					800.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
Checking wiring	RnR	20.00	0.00 %	20.00
Apply anti rust	RnR	100.00	0.00 %	100.00
Remove and refix cushion upholstrey	RnR	80.00	0.00 %	80.00
Remove and refix rear windscreen glass	RnR	120.00	0.00 %	120.00
Remove and refix front and rear under carriage	RnR	250.00	0.00 %	250.00
Check wheel alignment	RnR	80.00	0.00 %	80.00
Panel beating	RnR	1000.00	0.00 %	1,000.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
RH front door pillar	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	1200.00	0.00 %	1,200.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 1,650.00

Paint Labor Subtotal 1,200.00

Labor Subtotal 2,850.00

Summary

Repair Cost 13,273.16

Discount(20 %) (2,654.63)

10,618.53

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 10,618.53