



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: HO WINNIE		Ref: CS/HSB23002594/Wvp3e2 Date: 12/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 4291A	Veh. Inspected	GBL 8498H
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S3M04K8W	Excess (\$)	0.00
Assign From	HO WINNIE	Assign Date	13/03/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE DX	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KDH2010216207	Colour	BLACK
Odometer	131378 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	HABILEAD	6 mm
L/H Front Tyre	195 R15	HABILEAD	6 mm
R/H Rear Tyre	195 R15	HABILEAD	6 mm
L/H Rear Tyre	195 R15	HABILEAD	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/03/2023	Inspection Date	28/04/2023
Survey held at	60 JALAN LAM HUAT #05-45 CARROS CENTRE		
Repairer	TECH CHOON AUTOMOTIVE PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	