


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

Xiao Terry

DATE : 13.03.2023

TO : HSBC MOTOR CLAIMS DEPTS
VEHICLE NO : SMV9009Y
MODEL : TOYOTA LEXUS IS250
DATE OF ACCIDENT : 10.03.2023
TIME OF ACCIDENT : 10:35 HOURS

JTHBK262505088214

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Distorted</i>	1	\$ 1,685.00	\$ 1,685.00 <i>980</i>
2	FRONT BUMPER NUMBER PLATE GARNISH <i>Crack</i>	1	\$ 161.80	\$ 161.80
3	FRONT BUMPER FOG LAMP <i>New</i>	2	\$ 921.70	\$ 1,843.40
4	FRONT BUMPER FOG LAMP COVER GARNISH <i>2nd</i>	2	\$ 235.20	\$ 470.40 <i>250 (SW)</i>
5	FRONT BRACE PANEL <i>Bent</i>	1	\$ 128.00	\$ 128.00
6	FRONT BUMPER TOWING HOOD <i>New</i>	2	\$ 48.20	\$ 96.40
7	FRONT BUMPER BOTTOM GARNISH <i>Detached</i>	1	\$ 122.30	\$ 122.30
8	FRONT BUMPER TOP RUBBER SEAL <i>New</i>	1	\$ 78.20	\$ 78.20
9	FRONT BUMPER SIDE RETAINER <i>New</i>	2	\$ 125.80	\$ 251.60
10	FRONT BUMPER SPONGE <i>Missing</i>	1	\$ 196.40	\$ 196.40
11	FRONT BUMPER REINFORCEMENT <i>Detached</i>	1	\$ 738.10	\$ 738.10
12	RADIATOR GRILLE (UPPER) <i>Crack</i>	1	\$ 1,211.80	\$ 1,211.80 <i>850</i>
13	RADIATOR GRILLE CHROME <i>Crack</i>	1	\$ 332.60	\$ 332.60
14	HORN <i>1 piece left</i>	2	\$ 161.40	\$ 322.80 <i>161.40</i>
15	HEADLAMP LOWER BRACKET <i>Crack</i>	2	\$ 65.00	\$ 130.00
16	FRONT GRILLE (LOWER) <i>Crack</i>	1	\$ 295.00	\$ 295.00
17	FRONT GRILLE LOGO <i>New</i>	1	\$ 128.00	\$ 128.00
21	FRONT SUPPOR PANEL <i>Repair</i>	1	\$ 1,355.00	\$ 1,355.00

TO : **HSBC** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMV9009Y**
 MODEL : **TOYOTA LEXUS IS250**
 DATE OF ACCIDENT : 10.03.2023
 TIME OF ACCIDENT : 10:35 HOURS

22	FRONT SUPPORT PANEL TOP GARNISH <i>Dehid</i>	1	\$ 258.10	\$ 258.10	-
23	BONNET LOCK <i>men</i>	1	\$ 365.00	\$ 365.00	+
24	FRONT TEMPERATURE SENSOR <i>end</i>	1	\$ 255.00	\$ 255.00	✓
25	FRONT TEMPERATURE SENSOR BRACKET <i>HL</i>	1	\$ 68.00	\$ 68.00	+
26	FRONT AIR DUCT LH <i>for</i>	1	\$ 169.40	\$ 169.40	-
27	FRONT BONNET STOPPER <i>men</i>	2	\$ 38.00	\$ 76.00	+
18	AIR CON CONDENSER <i>men</i>	1	\$ 1,538.00	\$ 1,538.00	+
19	AIR CON CONDENSER SIDE AIR GUARD <i>for</i>	2	\$ 192.00	\$ 384.00	+
20	AIR CON CONDENSER LOWER AIR GUARD <i>for</i>	1	\$ 188.00	\$ 188.00	+

5157.70

TOTAL PRICE \$12,848.30

4641.93

LESS 10% \$ 1,284.83

SUB TOTAL PRICE \$11,563.47

SN: 250

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTALS/NETT	
1	FRONT NUMBER PLATE (SPECIAL TYPE) <i>and</i>	1	\$ 180.00	\$ 180.00	100-
2	FRONT BUMPER CLIP (SET) <i>men</i>	1	\$ 120.00	\$ 120.00	30
3	FRONT BUMPER BOTTOM GARNISH CLIP (SET) <i>men</i>	1	\$ 80.00	\$ 80.00	30
4	FRONT BUMPER LOWER LID (SPECIAL TYPE) <i>could</i>	1	\$ 2,800.00	\$ 2,800.00	800
5	RADIATOR GRILLE CLIP (SET) <i>men</i>	1	\$ 80.00	\$ 80.00	30
6	FRONT SUPPORT PANEL TOP COVER GARNISH CLIP (SET) <i>men</i>	1	\$ 50.00	\$ 50.00	20
7	FRONT SUPPORT PANEL SEALANT <i>men</i>	1	\$ 80.00	\$ 80.00	+
8	FRONT ENGINE UNDER COVER CLIP (SET) <i>men</i>	1	\$ 80.00	\$ 80.00	30
9	FRONT FENDER COWLING CLIP (SET) <i>men</i>	1	\$ 80.00	\$ 80.00	+
10	BONNET (CARBON FIBER) <i>Dehid</i>	1	\$ 8,600.00	\$ 8,600.00	2500
11	HEADLAMP LED (SET) <i>could</i>	1	\$ 6,800.00	\$ 6,800.00	✓ 5000
12	HEADLAMP TOP GARNISH (CARBON FIBER) <i>men</i>	1	\$ 250.00	\$ 250.00	200
13	CONDENSER AIR GUARD CLIP <i>men</i>	1	\$ 80.00	\$ 80.00	+
14	COOLANT <i>men</i>	1	\$ 80.00	\$ 80.00	+
15	FOGLAMP LED (SET) <i>and</i>	1	\$ 850.00	\$ 850.00	650

9390

TO : **HSBC** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMV9009Y**
MODEL : **TOYOTA LEXUS IS250**
DATE OF ACCIDENT : 10.03.2023
TIME OF ACCIDENT : 10:35 HOURS

TOTAL \$20,210.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	700
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	400
3	REFOCUS HEADLAMP BEAM	\$ 80.00	30
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS	\$ 120.00	60
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60
6	WIRING AND BULB CHECK	\$ 250.00	x
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	x

TOTAL \$ 4,080.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 31,773.47
TOTAL LABOUR COST : \$ 4,080.00
TOTAL REPAIR COST : \$ 35,853.47

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
R/S 15/03/23.
08 Days.

total 15531.93

L/S: 12.41c

12.41c