

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD		Ref:	CS3/SMR23002614/Wny3m4	
	60 WOODLANDS II E4SINGAPORE 75			Date:	19/04/2023	
				Code:	SMR	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMB 1524J	Veh. Inspected	k	SKV 5211D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	BUS/03/23/5014	Excess (\$)		0.00	
	Assign From	ASHLENE	Assign Date		13/03/2023	
2.	Vehicle Particulars & Condition					
	Make & Model	HONDA VEZEL 1.5X	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	RU11108542	Colour		WHITE	
	Odometer	80035 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/50 R18	YOKOHAMA		7 mm	
	L/H Front Tyre	225/50 R18	YOKOHAMA		7 mm	
	R/H Rear Tyre	225/50 R18	YOKOHAMA		7 mm	
	L/H Rear Tyre	225/50 R18	YOKOHAMA		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
5.	General Information					
	Accident Date	10/03/2023	Inspect Date /	Time	06/04/2023 (10:57 AM)	
	Survey held at	14 ANG MO KIO STREET 63 BL	K B 569116			
	Repairer	Repairer ASSURE AUTO ASSIST PTE LTD				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,700-\$4,500					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/SMR23002614/Wny3m4

Inspected By

MUHAMMAD AKID BIN MOHAMED KAMAL

K.K.LAU CPT(RET)

Asst. Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser