

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23002624/TNP3E2**Date:** 05/07/2023**REFERENCE**

Insured/Claimant: MUHAMMAD HAZWAN SYAKIR BIN SULAIMAN

Policy No: 7220123179

Date of Loss: 28/02/2023

Nature of Claim: OD Claim No: 6455669352SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNH4871T**

Make & Model: AUDI A4, 2.0 TFSI S-TRONIC (A)

Engine No: DEM036425

Reg. Date: 31/10/2022 (Man. Year: 2021)

Chassis No: WAUZZZF43NA013772

Colour: Black

Odometer: 11154 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$190,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17

Rear Tyre Size: 225/50 R17

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,069.00	3,072.88	10,996.12	78.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,132.00	1,602.00	8,530.00	84.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,201.00	4,674.88	19,526.12	80.68
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	23,101.00	3,574.88	19,526.12	84.52
+ GST 8.00/8.00% (S\$)	1,848.08	285.99	1,562.09	84.53
Nett Amount (S\$)	24,949.08	3,860.87	21,088.21	84.53

INSPECTION

Date of Assignment: 14/03/2023

Date Inspected: 14/03/2023

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	2,642.00 FS	*2,113.60 FS
2	1	*REAR BUMPER FIXING PARTS	Not Necessary	184.00 FS	*- FS
3	1	*REAR BUMPER SECURING STRIP	Necessary	133.00 FS	*106.00 FS
4	1	*REAR BUMPER SECURING STRIP	Not Necessary	264.00 FS	*- FS
5	1	*REAR BUMPER SPOILER	Deformed	292.00 FS	*233.60 FS
6	1	*REAR BUMPER BRACKET - RH	Deformed	241.00 FS	*192.40 FS
7	1	*REAR BUMPER REFLECTOR - LH / RH	O/S Cracked / N/S NotNecessary	102.00 FS	*81.12 FS
8	1	*REAR OUTER TAIL LIGHT - RH	Not Necessary	1,200.00 FS	*- FS
9	1	*REAR OUTER TAIL LIGHT TRIM - RH	Not Necessary	36.00 FS	*- FS
10	1	*REAR INNER TAIL LIGHT - RH	Not Necessary	1,200.00 FS	*- FS
11	1	*REAR INNER TAIL LIGHT TRIM - RH	Not Necessary	36.00 FS	*- FS
12	1	*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,197.00 FS	*- FS
13	2	*REAR BUMPER IMPACT BAR GASKET - LH / RH	Not Necessary	34.00 FS	*- FS
14	1	*REAR BUMPER GUIDE SECTION - RH UPPER	Not Necessary	54.00 FS	*- FS
15	2	*REAR BUMPER GUIDE SECTION - LH / RH LOWER	Not Necessary	54.00 FS	*- FS
16	2	*REAR BUMPER HOLDING STRAP - LH / RH	Not Necessary	200.00 FS	*- FS
17	2	*REAR PARKING AID SENSOR - INNER / OUTER	Not Necessary	543.00 FS	*- FS
18	4	*REAR PARKING AID SEAL RING	Not Necessary	11.00 FS	*- FS
19	1	*SET REAR BUMPER WIRING	Not Necessary	452.00 FS	*- FS
20	1	*REAR BOOT LID OPENING CONTROL UNIT	Not Necessary	491.00 FS	*- FS
21	1	*REAR TAILGATE OPENING SENSOR LINE	Not Necessary	230.00 FS	*- FS
22	1	*REAR AERIAL KEY ACCESS	Not Necessary	123.00 FS	*- FS
23	1	*REAR SILENCER - RH	Not Necessary	1,700.00 FS	*- FS
24	1	*REAR SILENCER DUAL CLIP	Not Necessary	61.00 FS	*- FS
25	1	*EXHAUST SILENCER BRACKET	Not Necessary	48.00 FS	*- FS
26	1	*EXHAUST TAIL PIPE TRIM - RH	Dented	406.00 FS	*324.80 FS
27	1	*REAR CROSS PANEL	Not Necessary	290.00 FS	*- FS
28	1	*RAER CROSS PANEL REINFORCEMENT	Not Necessary	565.00 FS	*- FS
29	1	*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
30	1	*CAVITY WAX	Not Necessary	140.00 FS	*- FS
31	1	*STONE CHIP	Not Necessary	180.00 FS	*- FS
32	1	*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
33	1	*SUNDRIES	Necessary	500.00 FS	*21.36 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 14,069.00 3,072.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
2	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	0.00
3	TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD REAR END PANELLING. TO REPAIR SPARE WHEEL HOUSING AND RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,200.00	500.00
4	TO RESPRAY REAR BUMPER, REAR END PANELLING, RHS REAR FENDER AND SPARE WHEEL HOUSING	New	3,500.00	550.00
5	TO RENEW RHS EXHAUST SILENCER AND ALIGN TO POSITION	New	480.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			10,132.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >