

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CC3/AIS23002625/RVY3Q2**Date:** 24/03/2023REFERENCEInsured/Claimant: MERCEDES-BENZ FLEET MANAGEMENT
SINGAPORE PTE LTD

Policy No: AIS/2022/0005592

Date of Loss: 27/02/2023

Nature of Claim: OD Claim No: 202332005886

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNJ2670J**

Make & Model: MERCEDES-BENZ GLA180, 1.6 (A)

Engine No: 28291480930169

Reg. Date: 05/01/2023 (Man. Year: 2022)

Chassis No: W1N2477842J456542

Colour: Black

Odometer: 8387 km

Engine Capacity: 1332 cc

Market Value/New Car Price: S\$207,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEYGeneral Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:CONDITION OF TYRES

Front Tyre Size: 235/55 R18

Rear Tyre Size: 235/55 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,734.62	5,261.62	473.00	8.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	2,260.00	680.00	23.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,674.62	7,521.62	1,153.00	13.29
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	7,974.62	6,821.62	1,153.00	14.46
+ GST 8.00/8.00% (S\$)	637.97	545.73	92.24	14.46
Nett Amount (S\$)	8,612.59	7,367.35	1,245.24	14.46

INSPECTION

Date of Assignment: 14/03/2023

Date Inspected: 14/03/2023 Inspected At:

Cycle & Carriage Industries Pte Ltd (Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Mar 2023)
Parts:	M1-SUV	MERCEDES-BENZ GLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNJ2670J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH/F HEADLAMP	Scratched	3,361.30 FS	*3,361.30 FS
2	1		*FRT BUMPER	Deformed	1,171.52 FS	*1,171.52 FS
3	1		*FRT CROSS MEMBER	Not Necessary	473.00 FS	*- FS
4	1		*FRT END SUPPORT MEMBER	Deformed	728.80 FS	*728.80 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					5,734.62	5,261.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
2	CHECK HEADLAMP WITH FOCUS ADJUSTMENT	New	120.00	120.00
3	REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH	New	1,440.00	960.00
4	RESPRAY FRONT BUMPER	New	1,000.00	800.00
Gross Labour Cost (\$\$)			2,940.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >