

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS23002633/HNY3M4**Date:** 05/04/2023**REFERENCE**

Insured/Claimant:	LIM JING JUN	Policy No:	SP2001652077	
Date of Loss:	10/03/2023	Nature of Claim:	OD	Claim No: 202332006199

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK7611D		
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS (A)	Engine No:	G4FGKU112694
Reg. Date:	24/04/2019 (Man. Year: 2019)	Chassis No:	KMHD841CMKU880765
Colour:	Blue	Odometer:	48516 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$79,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R19	Rear Tyre Size:	205/55 R19
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,520.90	5,946.80	1,574.10	20.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	730.00	400.00	35.40
Paintwork Labour	1,000.00	800.00	200.00	20.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,650.90	7,476.80	2,174.10	22.53
+ GST 8.00/8.00% (S\$)	772.07	598.14	173.93	22.53
Nett Amount (S\$)	10,422.97	8,074.94	2,348.03	22.53

INSPECTION

Date of Assignment:	14/03/2023	Present Location:	Success United Pte Ltd (HQ) SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921
Date Inspected:	14/03/2023	Inspected At:	
Estimated Period of Repair:	5.0 days		

Adjuster: Edward**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2023)
Parts:	143	HYUNDAI AD AVANTE 1.6 GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK7611D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Frt Bonnet (WCP)	Buckled	680.00 F	*680.00 F
2	2		*Frt Bonnet Hinge L/R (WCP)	Bent	90.00 F	*90.00 F
3	1		*Frt Bonnet Mechanism Lock (WCP)	Not Necessary	80.00 F	*- F
4	1		*Frt Bonnet Lock Cable (WCP)	Not Necessary	35.00 F	*- F
5	2		*Frt Headlamp L/R (WCP)	N/s Cracked/Cut/ O/s Cracked	2,760.00 F	*2,760.00 F
6	2		*Frt Headlamp Bracket L/R (WCP)	Broken	70.00 F	*70.00 F
7	1		*Frt Bumper (WCP)	Cracked	480.00 F	*480.00 F
8	1		*Frt Bumper Top Cover (WCP)	Not Necessary	18.00 F	*- F
9	1		*Frt Bumper Inner Top Bracket (WCP)	Cracked	60.00 F	*60.00 F
10	1		*Frt No.Plate Garnish (WCP)	Cracked	28.00 F	*28.00 F
11	2		*Frt Bumper Side Holder L/R (WCP)	Not Necessary	50.00 F	*- F
12	1		*Frt Bumper Inner Sponge (WCP)	Cracked	75.00 F	*75.00 F
13	1		*Frt Bumper Reinforcement (WCP)	Bent	250.00 F	*250.00 F
14	2		*Frt Bumper Lower Side Garnish Trim L/R (WCP)	Not Necessary	130.00 F	*- F
15	1		*Frt Grille Assy (WCP)	Cracked	480.00 F	*480.00 F
16	1		*Frt Bumper Weatherstrip (WCP)	Not Necessary	25.00 F	*- F
17	1		*Radiator Support Panel (WCP)	Not Necessary	330.00 F	*- F
18	1		*Radiator Support Panel Top Garnish (WCP)	Cracked	65.00 F	*65.00 F
19	1		*Horn (WCP)	Not Necessary	58.00 F	*- F
20	1		*Radiator (WCP)	Not Necessary	320.00 F	*- F
21	1		*Radiator Auxillary Fan Assy (WCP)	Not Necessary	300.00 F	*- F
22	1		*Aircon Condenser (WCP)	Dented	300.00 F	*300.00 F
23	1		*Air Intake Duct (WCP)	Not Necessary	85.00 F	*- F
24	1		*Frt Bumper Clips	Necessary	30.00 FS	*30.00 FS
25	1		*Frt No.Plate with Frame	Bent	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett.

	Sub Total (\$\$)	6,844.00	5,413.00
	+ Margin on L,N Items 10.00/10.00% (\$\$)	676.90	533.80
	Total Parts (\$\$)	7,520.90	5,946.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To putty & respray painting on bonnet, bumper , frt fender LH, frt door LH.	New	1,000.00	800.00
<u>Labour Items</u>				
2	To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.	New	800.00	600.00
3	To remove, rearrange electrical wirings, check lighting.	New	80.00	30.00
4	To remove, replace aircon parts, vacuum refill gas & renew coolant.	New	250.00	100.00
Gross Labour Cost (\$\$)			2,130.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >