

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	SU230062
Policy No:	SP2001652077	Date of Loss:	10/03/2023
Vehicle Reg. No.:	SMK7611D	Driveable?	
Driver Age/Info:	36 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	Lim Jing Jun	Contact No:	+6591451355
Driver:	Lim Jing Jun		
Make/Model:	HYUNDAI AD AVANTE, 1.6 GLS (A)	Vehicle Reg. Date:	24/04/2019
Vehicle Colour:	Blue		
Engine No:	G4FGKU112694	Chassis No:	KMHD841CMKU880765
Odometer:	48516 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	SUCCESS UNITED PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	7,520.90
Miscellaneous Items	0.00
Labour	1,130.00
Paintwork Labour	1,000.00
Towing	0.00
Gross Total (\$\$)	9,650.90
+ GST 8.00% (\$\$)	772.07
Nett Amount (\$\$)	10,422.97

This claim is handled by: **LAW YI TING**

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Mar 2023)
Parts:	143	HYUNDAI AD AVANTE 1.6 GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Success United Pte Ltd/SMK7611D/13/03/2023 15:49	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Frt Bonnet	0.00	0.00	*680.00 F
2	2		*Frt Bonnet Hinge L/R	0.00	0.00	*90.00 F
3	1		*Frt Bonnet Mechanism Lock	0.00	0.00	*80.00 F
4	1		*Frt Bonnet Lock Cable	0.00	0.00	*35.00 F
5	2		*Frt Headlamp L/R	0.00	0.00	*2,760.00 F
6	2		*Frt Headlamp Bracket L/R	0.00	0.00	*70.00 F
7	1		*Frt Bumper	0.00	0.00	*480.00 F
8	1		*Frt Bumper Top Cover	0.00	0.00	*18.00 F
9	1		*Frt Bumper Inner Top Bracket	0.00	0.00	*60.00 F
10	1		*Frt No.Plake Garnish	0.00	0.00	*28.00 F
11	2		*Frt Bumper Side Holder L/R	0.00	0.00	*50.00 F
12	1		*Frt Bumper Inner Sponge	0.00	0.00	*75.00 F
13	1		*Frt Bumper Reinforcement	0.00	0.00	*250.00 F
14	2		*Frt Bumper Lower Side Garnish Trim L/R	0.00	0.00	*130.00 F
15	1		*Frt Grille Assy	0.00	0.00	*480.00 F
16	1		*Frt Bumper Weatherstrip	0.00	0.00	*25.00 F
17	1		*Radiator Support Panel	0.00	0.00	*330.00 F
18	1		*Radiator Support Panel Top Garnish	0.00	0.00	*65.00 F
19	1		*Horn	0.00	0.00	*58.00 F
20	1		*Radiator	0.00	0.00	*320.00 F
21	1		*Radiator Auxillary Fan Assy	0.00	0.00	*300.00 F
22	1		*Aircon Condenser	0.00	0.00	*300.00 F
23	1		*Air Intake Duct	0.00	0.00	*85.00 F
24	1		*Frt Bumper Clips	0	0.00	*30.00 FS
25	1		*Frt No.Plake with Frame	0	0.00	*45.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	6,844.00
+ Margin on L,N Items 10.00% (\$\$)	676.90

Total Parts (\$\$)	7,520.90
---------------------------	-----------------

Success United Pte Ltd/SMK7611D/13/03/2023 15:49. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	To putty & respray painting on bonnet, bumper , frt fender LH, frt door LH.	New	1,000.00
Labour Items			
2	To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.	New	800.00
3	To remove, rearrange electrical wirings, check lighting.	New	80.00
4	To remove, replace aircon parts, vacuum refill gas & renew coolant.	New	250.00
Gross Labour Cost (\$)			2,130.00

Success United Pte Ltd/SMK7611D/13/03/2023 15:49. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >