

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600**Our File No:** CS/ICS23002638/RVY3E2**Date:** 20/07/2023**REFERENCE**

Insured/Claimant:	TAN JIAN ZHONG	Policy No:	MPC22P00302400	
Date of Loss:	03/03/2023	Nature of Claim:	OD	Claim No: DMPC2300145H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBN8829B		
Make & Model:	MERCEDES-BENZ C200 AMG LINE (R18 LED), 2.0 (A)	Engine No:	27492030206316
Reg. Date:	22/12/2014 (Man. Year: 2014)	Chassis No:	WDD2050422F042080
Colour:	White	Odometer:	110523 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	S\$63,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,720.00	5,340.50	379.50	6.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	1,130.00	450.00	28.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,300.00	6,470.50	829.50	11.36
Approved Total (Overridden) (S\$)		5,150.00		
(S\$)	7,300.00	5,150.00	2,150.00	29.45
+ GST 8.00/8.00% (S\$)	584.00	412.00	172.00	29.45
Nett Amount (S\$)	7,884.00	5,562.00	2,322.00	29.45

INSPECTION

Date of Assignment:	13/03/2023	Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	15/03/2023	Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Jul 2023)	
Parts:	N/A	MERCEDES-BENZ C200 AMG LINE (R18 LED) 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBN8829B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER (WCP)	Deformed	800.00 F	*800.00 F
2	1		*FRT BUMPER RETAINER RH (WCP)	Not Necessary	12.00 F	*- F
3	1		*FRT BUMPER INNER BRACKET RH (WCP)	Not Necessary	47.00 F	*- F
4	1		*FRT BUMPER UPPER CTR BRACKET (WCP)	Not Necessary	52.00 F	*- F
5	1		*FRT BUMPER SPONGE (WCP)	Not Necessary	80.00 F	*- F
6	10		*FRT BUMPER CLIP (WCP)	Necessary	50.00 F	*50.00 F
7	1		*FRT GRILLE BASE (WCP)	Not Necessary	64.00 F	*- F
8	1		*FRT HEADLAMP RH (WCP)	Cracked	2,370.00 F	*2,370.00 F
9	1		*FRT HEADLAMP PANEL RH (WCP)	Not Necessary	90.00 F	*- F
Supplementary #1						
10	1		*FRT UPPER SUPPORT PANEL (WCP)	Cracked	180.00 F	*180.00 F
11	1		*FRT HEADLAMP CONTROL UNIT RH (WCP)	Shorted	650.00 F	*650.00 F
12	1		*FRT HEADLAMP BALLAST MODULE (WCP)	Shorted	380.00 F	*380.00 F
13	1		*FRT BUMPER REINFORCEMENT SIDE BRACKET RH (WCP)	Cracked	50.00 F	*50.00 F
14	1		*FRT SUPPORT TOP PANEL (WCP)	Bent	375.00 F	*375.00 F

F=Franchise part.

Sub Total (\$)	5,200.00	4,855.00
+ Margin on L,N Items 10.00/10.00% (\$)	520.00	485.50
Total Parts (\$)	5,720.00	5,340.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK FRT BOONET,FRT FENDER RH,WELD,REMOVE & FIX ON ABOVE PARTS	New	600.00	400.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	700.00	600.00
3	TO CHECK WIRING	New	30.00	30.00
4	TO DIAGNOSE & RESET FAULT CODE	New	250.00	100.00
Gross Labour Cost (\$\$)			1,580.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >