

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTChina Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909**Our File No:** CS/CTI23002646/KCP3E2**Date:** 04/07/2023**REFERENCE**

Insured/Claimant:	CHIN MEE YOKE	Policy No:	DMPCSNW00280642200
Date of Loss:	10/03/2023	Nature of Claim:	OD
		Claim No:	SNM23D201846/C01/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT3273L		
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Engine No:	R16B22000668
Reg. Date:	25/10/2017 (Man. Year: 2017)	Chassis No:	MRHFC5650HT000301
Colour:	Metallic Dark Blue	Odometer:	75820 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	S\$73,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45ZR17	Rear Tyre Size:	225/45ZR17
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,387.00	8,610.00	10,777.00	55.59
Miscellaneous Items	40.00	40.00	0.00	0.00
Labour	2,633.40	1,180.20	1,453.20	55.18
Paintwork Labour	1,294.73	655.22	639.51	49.39
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,355.13	10,485.42	12,869.71	55.10
- Excess (S\$)	0.00	3,500.00	-3,500.00	
(S\$)	23,355.13	6,985.42	16,369.71	70.09
+ GST 8.00/8.00% (S\$)	1,868.41	558.83	1,309.58	70.09
Nett Amount (S\$)	25,223.54	7,544.25	17,679.29	70.09

INSPECTION

Date of Assignment:	14/03/2023	Present Location:	Ding Auto Pte Ltd (HQ)
			Ding Auto Pte Ltd (HQ)
Date Inspected:	14/03/2023	Inspected At:	176 Sin Ming Drive #04-06, Sin Ming Autocare
			Singapore 575721
Estimated Period of Repair:	14.0 days		

Adjuster: KENNETH KONG**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2023)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT3273L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BADGE CIVIC (NPA)	Not Necessary	0.00 F	*- F
2	1	NA	*BBS FORGED RIMS SET	Dented	1,800.00 F	*650.00 FS
3	1	NA	*BOOTLID	Repair	380.00 F	*- F
4	1	NA	*COMPL REAR AXLE SUPP	Bent	430.00 F	*420.00 F
5	1	NA	*FR HEADLAMP BCKT LHS	Serviceable	25.00 F	*- F
6	1	NA	*FR HEADLAMP BCKT RHS	Serviceable	25.00 F	*- F
7	1	NA	*FRONT BUMPER	Buckled	280.00 F	*280.00 F
8	1	NA	*FRONT STABILISER	Serviceable	130.00 F	*- F
9	1	NA	*FRT ASSEMBLY SUPPORT	Repair	920.00 F	*- F
10	1	NA	*L/DOOR MIRROR ASSY	Serviceable	300.00 F	*- F
11	1	NA	*L/DOOR MIRROR HSG	Serviceable	32.00 F	*- F
12	1	NA	*L/DRIVE SHAFT	Repair	620.00 F	*- F
13	1	NA	*L/F DOOR HANDLE TRIM	Serviceable	20.00 F	*- F
14	1	NA	*L/F DOOR OUT HANDLE	Serviceable	90.00 F	*- F
15	1	NA	*L/F DOOR SEAL	Distorted	58.00 F	*58.00 F
16	1	NA	*L/F HEADLAMP CPL	Mtg Cracked	520.00 F	*520.00 F
17	1	NA	*L/F INN DOOR SEAL FR	Serviceable	55.00 F	*- F
18	1	NA	*L/F LOWER DOOR HINGE	Repair	35.00 F	*- F
19	1	NA	*L/F LWR CONTROL ARM	Serviceable	175.00 F	*- F
20	1	NA	*L/F OUT BUMPER BRKT	Distorted	12.00 F	*15.00 F
21	1	NA	*L/FR SHOCK ABSORBER	Serviceable	180.00 F	*- F
22	1	NA	*L/FR TYRE (40%)	Cut	175.00 F	*70.00 FS
23	1	NA	*L/F STEERING KNUCKLE	Serviceable	170.00 F	*- F
24	1	NA	*L/F UPP CNTRL ARM RR	Bent	65.00 F	*60.00 F
25	1	NA	*L/F UPPER DOOR HINGE	Repair	35.00 F	*- F
26	1	NA	*L/F WHEELHOUSE COVER	Distorted	60.00 F	*60.00 F
27	1	NA	*L/F WINDOW MOULDING	Serviceable	38.00 F	*- F
28	1	NA	*L/F WING	Bent	200.00 F	*200.00 F
29	1	NA	*L/F WING BRACKET FRT	Repair	30.00 F	*- F
30	1	NA	*L/QTR WDW BOND KIT (NPA)	Not Necessary	0.00 F	*- F
31	1	NA	*L/R BUMPER BRACKET	Distorted	14.00 F	*14.00 F
32	1	NA	*L/R COIL SPRING	Serviceable	120.00 F	*- F
33	1	NA	*L/R CONTROL ARM	Serviceable	65.00 F	*- F
34	1	NA	*L/R DOOR	Bent	550.00 F	*550.00 F
35	1	NA	*L/R DOOR CHECK	Serviceable	40.00 F	*- F
36	1	NA	*L/REPEATER LAMP CPL	Cut	30.00 F	*30.00 F
37	1	NA	*L/R HINGE	Repair	36.00 F	*- F
38	1	NA	*L/R LAMP PANEL	Repair	55.00 F	*- F
39	1	NA	*L/R LOWER AXLE LINK	Serviceable	40.00 F	*- F
40	1	NA	*L/R LOWER DOOR HINGE	Repair	35.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1	NA	*L/R OUTER LAMP CPL	Serviceable	180.00 F	*- F
42	1	NA	*L/R OUTER SHACKLE	Serviceable	40.00 F	*- F
43	1	NA	*L/RR SHOCK ABSORBER	Bent	140.00 F	*140.00 F
44	1	NA	*L/RR SIDE PANEL	Repair	570.00 F	*- F
45	1	NA	*L/RR TYRE (50%)	Cut	175.00 F	*87.50 FS
46	1	NA	*L/R STRG KNUCKLE	Serviceable	165.00 F	*- F
47	1	NA	*L/R UPPER AXLE LINK	Serviceable	60.00 F	*- F
48	1	NA	*L/R UPPER DOOR HINGE	Repair	35.00 F	*- F
49	1	NA	*L/R WHEELHOUSE COVER	Serviceable	62.00 F	*- F
50	1	NA	*L/R WINDOW MOULDING	Serviceable	38.00 F	*- F
51	1	NA	*L/SILL PANEL COVER	Serviceable	120.00 F	*- F
52	1	NA	*L/TIE ROD BALL JOINT	Serviceable	50.00 F	*- F
53	1	NA	*LEFT FRONT DOOR	Bent	570.00 F	*570.00 F
54	1	NA	*LEFT HINGE COVER	Serviceable	11.00 F	*- F
55	1	NA	*R/DOOR MIRROR ASSY	Cracked	300.00 F	*300.00 F
56	1	NA	*R/DOOR MIRROR HSG	Missing	32.00 F	*35.00 F
57	1	NA	*R/DRIVE SHAFT	Bent	620.00 F	*620.00 F
58	1	NA	*R/F BUMPER OUT BRKT	Distorted	12.00 F	*15.00 F
59	1	NA	*R/F DOOR HANDLE TRIM	Serviceable	20.00 F	*- F
60	1	NA	*R/F DOOR OUT HANDLE	Serviceable	90.00 F	*- F
61	1	NA	*R/F DOOR SEAL	Cut	58.00 F	*58.00 F
62	1	NA	*R/F HEADLAMP CPL	Serviceable	520.00 F	*- F
63	1	NA	*R/F INN DOOR SEAL FR	Cut	55.00 F	*15.00 F
64	1	NA	*R/F LOWER DOOR HINGE	Repair	35.00 F	*- F
65	1	NA	*R/F LWR CONTROL ARM	Distorted	175.00 F	*175.00 F
66	1	NA	*R/FR SHOCK ABSORBER	Bent	180.00 F	*180.00 F
67	1	NA	*R/FR TYRE (40%)	Punctured	175.00 F	*70.00 FS
68	1	NA	*R/F STEERING KNUCKLE	Bent	170.00 F	*170.00 F
69	1	NA	*R/F UPP CNTRL ARM RR	Distorted	65.00 F	*60.00 F
70	1	NA	*R/F UPPER DOOR HINGE	Repair	35.00 F	*- F
71	1	NA	*R/F WHEELHOUSE COVER	Cracked	60.00 F	*60.00 F
72	1	NA	*R/F WINDOW MOULDING	Serviceable	38.00 F	*- F
73	1	NA	*R/F WING	Bent	200.00 F	*200.00 F
74	1	NA	*R/F WING BRACKET FRT	Repair	30.00 F	*- F
75	1	NA	*R/QTR WDW BOND KIT (NPA)	Not Necessary	0.00 F	*- F
76	1	NA	*R/R BUMPER BRACKET	Distorted	14.00 F	*14.00 F
77	1	NA	*R/R COIL SPRING	Serviceable	120.00 F	*- F
78	1	NA	*R/R CONTROL ARM	Bent	65.00 F	*65.00 F
79	1	NA	*R/R DOOR	Bent	550.00 F	*550.00 F
80	1	NA	*R/R DOOR CHECK	Serviceable	40.00 F	*- F
81	1	NA	*R/REPEATER LAMP CPL	Cracked	30.00 F	*30.00 F
82	1	NA	*R/R HINGE	Repair	36.00 F	*- F
83	1	NA	*R/R LAMP PANEL	Repair	55.00 F	*- F
84	1	NA	*R/R LOWER AXLE LINK	Bent	40.00 F	*40.00 F
85	1	NA	*R/R LOWER DOOR HINGE	Repair	35.00 F	*- F
86	1	NA	*R/R OUTER LAMP CPL	Serviceable	180.00 F	*- F
87	1	NA	*R/R OUTER SHACKLE	Serviceable	40.00 F	*- F
88	1	NA	*R/RR SHOCK ABSORBER	Bent	140.00 F	*140.00 F
89	1	NA	*R/RR SIDE PANEL	Repair	570.00 F	*- F
90	1	NA	*R/RR TYRE (50%)	Cut	175.00 F	*87.50 FS
91	1	NA	*R/R STRG KNUCKLE	Bent	165.00 F	*165.00 F
92	1	NA	*R/R UPPER AXLE LINK	Distorted	60.00 F	*65.00 F
93	1	NA	*R/R UPPER DOOR HINGE	Repair	35.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
94	1	NA	*R/R WHEELHOUSE CVR	Repair	62.00 F	*- F
95	1	NA	*R/R WINDOW MOULDING	Dented	38.00 F	*36.00 F
96	1	NA	*R/SILL PANEL COVER	Serviceable	120.00 F	*- F
97	1	NA	*R/TIE ROD BALL JOINT	Bent	50.00 F	*50.00 F
98	1	NA	*REAR BUMPER	Buckled / Dented	580.00 F	*340.00 F
99	1	NA	*REAR SCREEN BOND KIT (NPA)	Not Necessary	0.00 F	*- F
100	1	NA	*REAR STABILISER	Serviceable	130.00 F	*- F
101	1	NA	*RIGHT FRONT DOOR	Bent	570.00 F	*550.00 F
102	1	NA	*RIGHT HINGE COVER	Serviceable	11.00 F	*- F
103	1	NA	*STEERING GEAR	Serviceable	1,750.00 F	*- F
104	1	NA	*SUNDRY PARTS (NPA)	Not Necessary	0.00 F	*- F
Supplementary #1						
105	1		*ENGINE LOWER COVER	Cracked	180.00 F	*180.00 F
106	1		*FRONT WHEEL BEARING RHS	Necessary	90.00 F	*90.00 F
Supplementary #2						
107	1		*FRONT SPEED SENSOR RHS	Dented	85.00 F	*85.00 F
108	1		*FRONT DISC ROTOR RHS	Warped	140.00 F	*140.00 F
109	1		*FRONT DISC ROTOR LHS	Warped	140.00 F	*140.00 F
110	1		*REAR WHEEL BEARING RHS	Bent	160.00 F	*160.00 F

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	19,387.00	8,610.00
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Supplementary #2</u>				
1	1	WHEEL ALIGNMENT	40.00	40.00
Sub Total (S\$)			40.00	40.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	995.40	432.60
2	Total Paint Materials	New	299.33	222.62
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	2,633.40	1,180.20
Gross Labour Cost (S\$)			3,928.13	1,835.42

Report was unsubmitted during this print-out.

< END OF ESTIMATES >