4/5/23, 4:53 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III23002660/UNY3E2

Date: 05/04/2023

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0007084

Claimant Vehicle SLP4961Z Insured Vehicle No: SLD5525G

No: SLP4901Z Insured vehicle No: SLD5525G

Date of Loss: 13/03/2023 Nature of Claim: TP Claim No: MFL2023D0003047

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP4961Z

 Make & Model:
 TOYOTA HARRIER, 2.0 PREMIUM CVT (A)
 Engine No:
 3ZRB937984

 Reg. Date:
 07/06/2017 (Man. Year: 2016)
 Chassis No:
 ZSU600095021

 Colour:
 Black
 Odometer:
 204746 km

Engine Capacity: 1986 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18
Front Left Side: Giti 6 mm Rear Left Side: Hankook 6 mm
Front Right Side: Giti 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	0.00	0.00	0.00	
	Approved Total (Overridden) (S\$)		3,800.00		
	Nett Amount (S\$)	0.00	3,800.00	-3,800.00	

INSPECTION

Date of Assignment: 14/03/2023

Hua Meng Spray Painting Workshop (HQ)

Date Inspected: 14/03/2023 Inspected At: No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/5/23, 4:53 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Apr 2023)

Parts: M1-SUV TOYOTA HARRIER 2.0 PREMIUM CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLP4961Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

4/5/23, 4:53 PM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >