

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123002675/ANY3Q2**Date:** 05/06/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SLZ6712K **Insured Vehicle No :** GBL1155T

Date of Loss: 11/03/2023 Nature of Claim: TP Claim No: CDMCG23000616

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ6712K**

Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A) Engine No: 2ZR8422877

Reg. Date: 14/05/2018 (Man. Year: 2018) Chassis No: ZYX102116774

Colour: White Odometer: 84436 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,126.72	6,434.07	1,692.65	20.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	2,320.00	1,060.00	31.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,506.72	8,754.07	2,752.65	23.92
Approved Total (Overridden) (S\$)		7,000.00		
Nett Amount (S\$)	11,506.72	7,000.00	4,506.72	39.17

INSPECTION

Date of Assignment: 14/03/2023

Date Inspected: 15/03/2023 Inspected At: Automobile Hub Enterprise
1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @
KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jun 2023)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ6712K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	855.10 FL	*855.10 FL
2	2		*REAR BUMPER SIDE HOLDER	Not Necessary	224.40 FL	*- FL
3	1		*REAR BUMPER SIDE GRILLE	O/S Torn	374.00 FL	*187.00 FL
4	2		*REAR BUMPER SIDE GRILLE REFLECTOR	Not Necessary	118.00 FL	*- FL
5	1		*REAR BUMPER TOW COVER	Not Necessary	27.70 FL	*- FL
6	1		*REAR BUMPER LOWER GARNISH	Deformed	465.10 FL	*465.10 FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	352.70 FL	*352.70 FL
8	2		*REAR BUMPER UNDERCOVER	Not Necessary	378.40 FL	*- FL
9	1		*REAR BUMPER LOWER GARNISH REFLECTOR	Cracked	145.40 FL	*145.40 FL
10	2		*REVERSE SENSOR	Damaged	500.00 FL	*500.00 FL
11	1		*REAR END PANEL	Dented	731.40 FL	*731.40 FL
12	1		*REAR END PANEL TOP GARNISH	Deformed	347.40 FL	*347.40 FL
13	1		*REAR END PANEL ANTENNA SENSOR	Damaged	106.90 FL	*106.90 FL
14	1		*TAILGATE	Dented	1,112.50 FL	*1,112.50 FL
15	1		*TAILGATE LOCK	Damaged	389.40 FL	*389.40 FL
16	1		*TAILGATE LOCK COVER	Deformed	29.40 FL	*29.40 FL
17	1		*TAILGATE LOCK STRIKER	Not Necessary	105.50 FL	*- FL
18	1		*TAILGATE WEATHERSTRIPE	Cut	371.40 FL	*371.40 FL
19	1		*TAILGATE INNER PULL POCKET	Deformed	38.40 FL	*38.40 FL
20	1		*TAILGATE OUTER GARNISH	Cracked	882.20 FL	*882.20 FL
21	1		*TAILGATE INNER TRIM BOARD	Cracked	386.70 FL	*386.70 FL
22	1		*TAILGATE GLASS MOULDING	Necessary	158.40 FL	*158.40 FL
23	1		*TOYOTA LOGO	Necessary	72.20 FL	*72.20 FL
24	1		*CHR WORDING	Necessary	55.60 FL	*55.60 FL
25	1		*HYBRID EMBLEM	Necessary	121.40 FL	*121.40 FL
26	1		*REAR EXHAUST PIPE	Not Necessary	987.90 FL	*- FL
27	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	45.00 FL	*- FL
28	1		*REAR EXHAUST PIPE GASKET	Not Necessary	45.40 FL	*- FL
29	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Necessary	110.90 FL	*- FL
30	1		*SPARE TYRE PANEL TOP COVER	Deformed	591.70 FL	*591.70 FL
31	1		*TOOLS TRAY SPONGE	Cracked	371.80 FL	*371.80 FL
32	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
33	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
34	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
35	1		*TAILGATE OUTER GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
36	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
37	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,752.30	8,502.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,625.58	2,068.03
Total Parts (\$\$)	8,126.72	6,434.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING	New	1,200.00	1,000.00
3	WIRING	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	80.00
5	TO REMOVE UPHOLSTERY	New	150.00	80.00
6	TO TRANSFER TAILGATE FITTINGS	New	150.00	60.00
7	TO REMOVE TAILGATE GLASS	New	180.00	120.00
8	TO REMOVE REVERSE SENSOR	New	100.00	50.00
9	TO REMOVE REAR CAMERA	New	100.00	50.00
10	TO REMOVER EAR VIDEO RECORDER	New	100.00	50.00
Gross Labour Cost (S\$)			3,380.00	2,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >