



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 7360Y

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|---------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | FRONT BUMPER | DISTORTED | 705.24 | 648.00 |
| 2 | FRONT BUMPER SIDE RETAINER @\$74.96 | TORN | 149.92 | 149.92 |
| 1 | FRONT BUMPER SPONGE | NOT NECESSARY | 120.00 | - |
| 1 | FRONT BUMPER RE ENFORCEMENT | NOT NECESSARY | 427.20 | - |
| 1 | FRONT GRILLE | NOT NECESSARY | 477.60 | - |
| 1 | HEADLAMP LH | NOT NECESSARY | 1,150.86 | - |
| 1 | HEADLAMP RH | GRAZED | 1,150.86 | 1,150.86 |
| 1 | BONNET | DENTED | 972.00 | 972.00 |
| 1 | BONNET LOGO | NECESSARY | 65.00 | 65.00 |
| 1 | BONNET INNER LOCK | NOT NECESSARY | 114.00 | - |
| 1 | BONNET INNER SEAL | NOT NECESSARY | 48.00 | - |
| 1 | SUPPORT PANEL | NOT NECESSARY | 1,547.88 | - |
| | LESS 25% DISCOUNT | | -1,732.14 | -746.45 |
| | | | 5,196.42 | 2,239.33 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | SET FRONT BUMPER CLIP (SN) | NECESSARY | 80.00 | 30.00 |
| 1 | SET FRONT GRILLE CLIPS (SN) | NOT NECESSARY | 80.00 | - |
| | | | 160.00 | 30.00 |
| <u>LABOUR</u> | | | | |
| | TO CHECK WIRING SYSTEM. | | 80.00 | 30.00 |
| | TO REPROGRAM AND RESET AFTER REPAIR. | NOT NECESSARY | 200.00 | - |
| | TO CUT & WEILD ON SUPPORT PANEL. TO PANEL BEAT AND STRAIGHTEN ON FRONT WHEEL HOUSING AND TO R&R FRONT BUMPER, HEADLAMP, BONNET AND OTHER ATTACHMENTS. | | 1,000.00 | 400.00 |
| | TO PUTTY AND RESPRAY FRONT BUMPER, BONNET, FRONT BOTH FENDERS, SUPPORT PANEL AND ACCIDENT AFFECTED AREA. | | 1,500.00 | 400.00 |
| | RUSTPROOFING. | | 200.00 | 30.00 |
| | | | 2,980.00 | 860.00 |
| GRAND TOTAL | | | 8,336.42 | 3,129.33 |

Report Ref No. CS3/LPC22011587/Tvy3e2-1



| | | | |
|---|--|--|----------|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 2,500.00 |
|---|--|--|----------|

Report Ref No. CS3/LPC22011587/Tvy3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.