

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/III22012204/TVY3E2-1**Date:** 17/03/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MFL0003414\_03  
**Claimant Vehicle No :** SNB7678Y **Insured Vehicle No :** SNG1757R  
 Date of Loss: 01/12/2022 Nature of Claim: TP Claim No: MFL2022D0011281

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNB7678Y**  
 Make & Model: TOYOTA CAMRY, 2.5 HYBRID 4DR SEDAN ELEGANCE (A) Engine No: A25A5644171  
 Reg. Date: 14/09/2021 (Man. Year: 2021) Chassis No: JTNB23HK503105069  
 Colour: Grey Odometer: 8983 km  
 Engine Capacity: 2487 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45 R18 Rear Tyre Size: 235/45 R18  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,619.70	2,856.45	1,763.25	38.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	1,340.00	910.00	40.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,869.70</b>	<b>4,196.45</b>	<b>2,673.25</b>	<b>38.91</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,350.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,869.70</b>	<b>3,350.00</b>	<b>3,519.70</b>	<b>51.24</b>

INSPECTION

Date of Assignment: 06/12/2022  
 Date Inspected: 07/12/2022 Inspected At: Tampines Auto Services (HQ)  
 BLK 9002 TAMPINES ST 93, #01-34/36 INDUSTRIAL PARK A  
 Singapore 528836  
 Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 17 Mar 2023)
<b>Parts:</b>	143	TOYOTA CAMRY 2.5 HYBRID 4DR SEDAN ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNB7678Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	1,316.10 FL	*- FL
2	1		*BOOT LID EMBLEM (LOGO)	Necessary	85.20 FL	*85.20 FL
3	1		*BOOT LID EMBLEM (CAMRY)	Necessary	85.90 FL	*85.90 FL
4	1		*BOOT LID EMBLEM (HYBRID)	Necessary	65.10 FL	*65.10 FL
5	1		*BOOT LID REFLECTOR LH	Refit	429.50 FL	*- FL
6	1		*TAILLAMP LH	Cracked	861.50 FL	*861.50 FL
7	1		*TAILLAMP PANEL LH	Repair	226.10 FL	*- FL
8	1		*RR END PANEL	Distorted	777.80 FL	*777.80 FL
9	1		*RR BUMPER	Buckled	779.10 FL	*779.10 FL
10	1		*RR BUMPER SIDE GRILLE R/L	N/S Cut	71.80 FL	*35.90 FL
11	1		*RR BUMPER ULTRASONIC SENSOR LH	Short Circuit	437.00 FL	*250.00 FL
12	1		*RR BUMPER REFLECTOR LH	Cracked	71.40 FL	*71.40 FL
13	6		*RR BUMPER CLIP	Necessary	21.60 FL	*21.60 FL
14	1		*RR BUMPER RETAINER R/L	N/S Necessary	175.40 FL	*87.70 FL
15	1		*RR BUMPER SIDE BRACKET R/L	N/S Cracked/Necessary	137.40 FL	*68.70 FL
16	1		*RR BUMPER SPONGE	Dented / Cracked	106.50 FL	*106.50 FL
17	1		*RR BUMPER REINFORCEMENT	Dented	512.20 FL	*512.20 FL
18	1		*BOOT LID (NPA)	Repeated	0.00 FL	*- FL
19	1		*RR FENDER LH (NPA)	Repair	0.00 FL	*- FL
20	1		*RR FLOOR PANEL (NPA)	Repair	0.00 FL	*- FL
21	1		*RR CHASSIS MEMBER LH (NPA)	Repair	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>6,159.60</b>	<b>3,808.60</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	1,539.90	952.15
<b>Total Parts (\$)</b>	<b>4,619.70</b>	<b>2,856.45</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL ELECTRICAL WIRING SYSTEM FOR NECESSARY REPAIRS. TO CHECK REAR ELECTRICAL WIRING SYSTEM	New	50.00	30.00
2	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, ETC. FOR NECESSARY REPAIRS	New	80.00	60.00
3	TO REMOVE, REPLACE AND/OR TRANSFER REAR REVERSE SENSORS TO NEW BUMPER. (INCLUDE RESET/REPROGRAM CONTROL UNIT)	New	120.00	50.00
4	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00	600.00
5	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA	New	1,000.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>2,250.00</b>	<b>1,340.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >