



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBT 9661D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	BENT	245.00	245.00
1	MIRROR	SCRATCHED	98.00	98.00
1	HANDLE BALANCER	SCRATCHED	68.00	68.00
1	COMPLETE SIGNAL LIGHT RIGHT	SCRATCHED	138.00	138.00
1	FRONT SPORT RIM	NOT NECESSARY	295.00	-
1	TANK SIDE COVER RIGHT SIDE	SCRATCHED	285.00	285.00
1	HAND LIGHT SIDE COVER RIGHT	SCRATCHED	145.00	145.00
1	FUEL TANK SIDE COVER RIGHT	SCRATCHED	285.00	285.00
1	COMPLETE ENGINE GUARD	SCRATCHED	190.00	190.00
1	RIGHT REAR SIDE COVER	SCRATCHED	98.00	98.00
1	REAR MUDGUARD	CRACKED	165.00	165.00
	LESS 10% DISCOUNT		-	-171.70
			2,012.00	1,545.30
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT MUDGUARD (SN) (LOCAL REPAIR)	SCRATCHED	120.00	50.00
1	FRONT NO. PLATE (SN)	BENT	28.00	28.00
			148.00	78.00
	<u>LABOUR</u>			
	TOWING. }		35.00	40.00
	TOWING TO IDAC. }		35.00	-
	FORK REPAIR.		155.00	80.00
	LABOUR.		280.00	200.00
			505.00	320.00
	GRAND TOTAL		2,665.00	1,943.30

RECOMMENDED COST OF REPAIRS			1,943.30
------------------------------------	--	--	-----------------

Report Ref No. CS/FCI23002692/Rny3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.