

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	AUTOMOTIVE ENG	GRG. & MGT. DIVISION (TP)	F	Ref:	CS3/SPF23002694/Tvy3m4	
	FORCE) POLICE L	S SECTION (SPORE POLICE OGISTICS BASE (PLB) 1 SINGAPORE 438675	Ι	Date:	12/07/2023	
	ATTN: HAFIZUL FA	ARHAN	(Code:	SPF	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YL 6360L	Veh. Inspected		SLK 5878B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	ACS/105/009/2023/016	Excess (\$)		0.00	
	Assign From	HAFIZUL FARHAN	Assign Date		14/03/2023	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA VEZEL	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	RU11205883	Colour		BLUE	
	Odometer	60550 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	FIRENZA		6 mm	
	L/H Front Tyre	215/60 R16	FIRENZA		6 mm	
	R/H Rear Tyre	215/60 R16	FIRENZA		6 mm	
	L/H Rear Tyre	215/60 R16	FIRENZA		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DE	TAILS.			· · · · · · · · · · · · · · · · · · ·	
5.	General Information					
	Accident Date	20/02/2023	Inspect Date / T	ime	24/03/2023 (10:30 AM)	
	Survey held at	COMPASS GREEN (S) 498839				
-	Repairer	HOCK HENG				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					
5b.	,					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					