3/27/23, 10:06 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI23002699/KVP3Q2

**Date:** 27/03/2023

**REFERENCE** 

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MT103068

Claimant Vehicle Cuproco A Control of the Control

No: SHD5339A Insured Vehicle No: SMA7602H

Date of Loss: 11/03/2023 Nature of Claim: TP Claim No: M2301636

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHD5339A

 Make & Model:
 RENAULT LATITUDE, 2.0 L (A)
 Engine No:
 M9R8839C003398

 Reg. Date:
 31/08/2016 (Man. Year: 2015)
 Chassis No:
 VF1ABL15AUC283342

Colour: Metallic White/Red Odometer: 75972 km

Engine Capacity:
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

1995 cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Grenlander 9 mm Rear Left Side: Sailun 8 mm
Front Right Side: Grenlander 9 mm Rear Right Side: Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		9,241.59	1,401.24	7,840.35	84.84
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,910.00	480.00	4,430.00	90.22
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	14,151.59	1,881.24	12,270.35	86.71
	Approved Total (Overridden) (S\$)		1,500.00		
	(S\$)	14,151.59	1,500.00	12,651.59	89.40
	+ GST 8.00/8.00% (S\$)	1,132.13	120.00	1,012.13	89.40
	Nett Amount (S\$)	15,283.72	1,620.00	13,663.72	89.40

**INSPECTION** 

Date of Assignment: 20/03/2023

Date Inspected: TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

3/27/23, 10:06 AM Adjuster Report

## REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Mar 2023)

Parts: 143 RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD5339A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled / Dented	561.70 FL	*561.70 FL
2	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*-FL
3	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*-FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*-FL
5	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
6	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
7	1		*BUMPER LOWER REAR	Dented	411.90 FL	*411.90 FL
8	1		*BUMPER BEAM REAR	Repair	547.80 FL	*- FL
9	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*- FL
10	1		*BUMPER BEAM BRACKET RH REAR	Repair	114.50 FL	*- FL
11	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*- FL
12	1		*BUMPER REFLECTOR RH	Serviceable	16.60 FL	*- FL
13	1		*BOOT REFLECTOR LAMP LH (CRACKED)	Not Consistent With The Impact	277.70 FL	*- FL
14	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*- FL
15	1		*TAILLAMP LH	Serviceable	401.40 FL	*- FL
16	1		*TAILLAMP RH (CRACKED)	Not Consistent With The Impact	401.40 FL	*- FL
17	1		*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	*- FL
18	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
19	1		*BOOT REAR (BENT)	Not Consistent With The Impact	1,677.20 FL	*- FL
20	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
21	1		*BOOT LOCK	Repair	246.60 FL	*- FL
22	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*- FL
23	1		*BOOT STRUT LH	Serviceable	145.10 FL	*- FL
24	1		*BOOT STRUT RH	Serviceable	145.10 FL	*- FL
25	1		*BOOT HINGE LH	Repair	254.20 FL	*- FL
26	1		*BOOT HINGE RH	Repair	254.20 FL	*- FL
27	1		*BOOT BADGE RENAULT	Not Necessary	82.40 FL	*- FL
28	1		*BOOT BADGE	Not Necessary	95.80 FL	*- FL
29	1		*SET PARKING AID	Missing	700.00 FS	*400.00 FS
30	1		*REAR BUMPER CLIP	Necessary	65.00 FS	*65.00 FS
31	1		*REAR NUMBER PLATE WITH MOULDING	Serviceable	180.00 FS	*- FS
32	1		*REAR BUMPER ADVERTISEMENT	Necessary	100.00 FS	*60.00 FS
33	1		*REAR LH BUMPER RETAINER CLIP	Not Necessary	65.00 FS	*- FS
34	1		*REAR RH BUMPER RETAINER CLIP	Not Necessary	65.00 FS	*-FS
35	1		*REAR TAIL LAMP CLIP	Not Necessary	65.00 FS	*-FS
36	1		*END PANEL INNER TRIM CLIP	Not Necessary	60.00 FS	*-FS
37	1		*REAR BUMPER PROTECTOR	No such part	180.00 FS	*-FS
38	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*-FS
39	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*-FS
40	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*-FS

 $\label{eq:FF} \textit{F=Franchise part. S=SpcNett. L=ListItemDisc.}$ 

 Sub Total (S\$)
 10,050.66
 1,498.60

 - List Item Discount on L Items 10.00/10.00% (S\$)
 809.07
 97.36

**Total Parts (S\$)** 9,241.59 1,401.24

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	600.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	220.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUS AND REALIGN THE SAME	New ST	2,000.00	200.00
4	TO TRANSFER OF TAILGATE FITTING AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
8	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
	Gross Labo	our Cost (S\$)	4,910.00	480.00
	Report was unsubmitted during th	is print-out.		

< END OF ESTIMATES >