

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23002702/RVP3Q2**Date:** 18/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00056502200
<b>Claimant Vehicle No :</b>	SKM1859J	<b>Insured Vehicle No :</b>	GBL8399K
Date of Loss:	12/03/2023	Nature of Claim: TP	Claim No: SNM23D201914/C02/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKM1859J</b>		
Make & Model:	BMW 520I, 2.0 AT D/AB 2WD 4DR LED NAV (A)	Engine No:	A1810659N20B20B
Reg. Date:	28/01/2014 (Man. Year: 2013)	Chassis No:	WBA5A32010D334898
Colour:	Blue	Odometer:	117341 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,889.25	1,696.00	2,193.25	56.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,667.00	2,172.00	495.00	18.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,556.25</b>	<b>3,868.00</b>	<b>2,688.25</b>	<b>41.00</b>
<b>+ GST 8.00/8.00% (S\$)</b>	524.50	309.44	215.06	41.00
<b>Nett Amount (S\$)</b>	<b>7,080.75</b>	<b>4,177.44</b>	<b>2,903.31</b>	<b>41.00</b>

**INSPECTION**

Date of Assignment:	14/03/2023	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Date Inspected:	11/04/2023 Inspected At:	
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 May 2023)
Parts:	143	BMW 520I 2.0 AT D/AB 2WD 4DR LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKM1859J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*SET OF MOUNT	Not Necessary	49.50 FS	*- FS
3	1		*RR BUMPER BOTTOM CENTRE GUIDE	Not Necessary	142.80 FS	*- FS
4	1		*RR BUMPER CARRIER	Not Necessary	811.15 FS	*- FS
5	1		*ADAPTOR	Not Necessary	116.45 FS	*- FS
6	1		*REAR BUMPER CENTRE GUIDE	Not Necessary	199.90 FS	*- FS
7	1		*REAR BUMPER PRIMED (PDC)	Deformed	1,616.00 FS	*1,616.00 FS
8	10		*EXPANDING RIVET D=8MM	Not Necessary	11.50 FS	*- FS
9	10		*PLUG BLACK D=5MM	Not Necessary	9.50 FS	*- FS
10	1		*REAR LH REFLECTOR	Not Necessary	41.00 FS	*- FS
11	2		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	10.60 FS	*- FS
12	2		*BUMPER PDC SENSOR (A89 IMPERIABLAU)	Not Necessary	747.80 FS	*- FS
13	1		*(DG/SL) ADHESIVE SET K6	Not Necessary	53.05 FS	*- FS
					F=Franchise part. S=SpcNett.	
					Total Parts (S\$)	3,889.25 1,696.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER	New	1,275.00	850.00
2	TO RESPRAY REAR BUMPER	New	1,038.00	986.00
3	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
4	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
<b>Gross Labour Cost (S\$)</b>			<b>2,667.00</b>	<b>2,172.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >