

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23002704/KNP3Q2**Date:** 28/03/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00031672200

**Claimant Vehicle No :** SJE3762U **Insured Vehicle No :** GBL2668Z

Date of Loss: 08/03/2023 Nature of Claim: TP Claim No: SNM23D201826/C02/TAYHP

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SJE3762U**

Make & Model: HONDA STREAM, 1.8 L RSZ (A) Engine No: R18A1763650

Reg. Date: 23/04/2008 (Man. Year: 2007) Chassis No: RN61056916

Colour: Black Odometer: 261096 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17

Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,351.44	821.60	529.84	39.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	465.00	1,035.00	69.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,851.44</b>	<b>1,286.60</b>	<b>1,564.84</b>	<b>54.88</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,000.00</b>		
<b>(S\$)</b>	2,851.44	1,000.00	1,851.44	64.93
<b>+ GST 8.00/8.00% (S\$)</b>	228.12	80.00	148.12	64.93
<b>Nett Amount (S\$)</b>	<b>3,079.56</b>	<b>1,080.00</b>	<b>1,999.56</b>	<b>64.93</b>

**INSPECTION**

Date of Assignment: 15/03/2023

Date Inspected: 15/03/2023 Inspected At: 14 ANG MO KIO ST 63, BLOCK B  
SINGAPORE 569116  
Repairer:Kgc Workshop Pte Ltd (HQ)

Estimated Period of Repair: 2.0 days

**Adjuster:** KENNETH KONG**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Mar 2023)
Parts:	M1-MPV	HONDA STREAM 1.8 L RSZ (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJE3762U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Cracked	675.80 FL	*675.80 FL
2	2		*REAR BUMPER RETAINER RHS /LHS	Serviceable	76.80 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	No such part	485.50 FL	*- FL
4	1		*REAR BUMPER TOWING COVER	Dented	38.70 FL	*38.70 FL
5	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
6	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
					Sub Total (\$\$)	1,606.80 964.50
					- List Item Discount on L Items 20.00/20.00% (\$\$)	255.36 142.90
					Total Parts (\$\$)	1,351.44 821.60

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE ,REPLACE ,CUT ,WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR PARTS INCLUSIVE OF REPLACEMENT PARTS	New	600.00	200.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS (SPECIAL PAINT ,PEARL EFFECT)	New	600.00	200.00
3	TO REMOVE AND REFIT REAR PARKING SENSOR AND CONDUCT SAFE DISTANCE SETTING	New	100.00	50.00
4	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME	New	100.00	15.00
5	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	100.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,500.00</b>	<b>465.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >