



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO23002709/Uvy3m4 Date: 23/03/2023 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 4747Y	Veh. Inspected	GBJ 9558Y
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2301068/SYH	Excess (\$)	0.00
Assign From	BETTY WONG	Assign Date	15/03/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTFAT35Y30K213953	Colour	SILVER
Odometer	50080 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	GREENLANDER	7 mm
L/H Front Tyre	195 R15	GREENLANDER	7 mm
R/H Rear Tyre	155 R12 (D/D)	YOKOHAMA	7/7 mm
L/H Rear Tyre	155 R12 (D/D)	YOKOHAMA	7/7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/03/2023	Inspection Date	15/03/2023
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	