

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS6/AIS23002710/HVY3E2**Date:** 13/04/2023**REFERENCE**

Insured/Claimant:	TAN PECK SIAN JENNY	Policy No:	SP2000684732	
Date of Loss:	13/03/2023	Nature of Claim:	OD	Claim No: 202332006164

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBE3800M		
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Engine No:	FB20YE48472
Reg. Date:	29/12/2018 (Man. Year: 2018)	Chassis No:	JF1SJ5KC5JG112788
Colour:	Brown	Odometer:	103902 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	S\$86,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,433.00	3,762.00	671.00	15.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,360.00	650.00	710.00	52.21
Paintwork Labour	880.00	600.00	280.00	31.82
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,673.00	5,012.00	1,661.00	24.89
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	6,673.00	4,412.00	2,261.00	33.88
+ GST 8.00/8.00% (S\$)	533.84	352.96	180.88	33.88
Nett Amount (S\$)	7,206.84	4,764.96	2,441.88	33.88

INSPECTION

Date of Assignment:	15/03/2023	Present Location:	Vin's Motor Pte Ltd (Sin Ming)
Date Inspected:	15/03/2023	Inspected At:	Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	5.0 days		

Adjuster: Edward**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Apr 2023)
Parts:	M1-SUV	SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBE3800M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bumper (WCP)	Cut	380.00 F	*380.00 F
2	1		*Front bumper LH side retainer (WCP)	Distorted	10.00 F	*10.00 F
3	10		*Front bumper clips (WCP)	Necessary	20.00 F	*20.00 F
4	1		*Front LH headlamp (WCP)	Cracked	1,700.00 F	*1,700.00 F
5	1		*Front LH headlamp lower bracket (WCP)	Not Necessary	30.00 F	*- F
6	1		*Front LH fender (WCP)	Buckled	190.00 F	*190.00 F
7	1		*Front LH fender inner shield (WCP)	Distorted	80.00 F	*80.00 F
8	10		*Front LH fender inner shield clips (WCP)	Necessary	20.00 F	*20.00 F
9	1		*Front LH fender triangle cover (WCP)	Not Necessary	10.00 F	*- F
10	1		*Front LH fender insulator - Top (WCP)	Torn	20.00 F	*20.00 F
11	1		*Front LH fender lower protector (WCP)	Not Necessary	20.00 F	*- F
12	1		*Front LH door (WCP)	Buckled	600.00 F	*600.00 F
13	1		*Front LH door outer chrome moulding (WCP)	Cut	70.00 F	*70.00 F
14	1		*Front LH door top pillar frame sticker (WCP)	Necessary	40.00 F	*40.00 F
15	1		*Front LH door top hinge (WCP)	Scratched	30.00 F	*30.00 F
16	1		*Front LH door lower hinge (WCP)	Scratched	30.00 F	*30.00 F
17	1		*LH side mirror signal light (WCP)	Cracked	70.00 F	*70.00 F
18	1		*Front LH sport rim (WCP)	Not Necessary	550.00 F	*- F
19	1		*Front LH knuckle wheel bearing (WCP)	Damaged	160.00 F	*160.00 F

F=Franchise part.

Sub Total (\$\$)	4,030.00	3,420.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	403.00	342.00
Total Parts (\$\$)	4,433.00	3,762.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO SPRAY PAINTING	New	880.00	600.00
<u>Labour Items</u>				
2	To check wheel alignment	New	150.00	0.00
3	To remove and replace bearing	New	150.00	0.00
4	To reset headlamp system	New	280.00	50.00
5	TO REPAIR DAMAGES	New	780.00	600.00
Gross Labour Cost (\$)			2,240.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >