

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: YN 29365
 at Workshop m/s B2W
 of _____
 Insured: G3H 1851M
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: YN 29365 Yr Regn: 08/03/12
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Hino (M) X24700R c.c. 4009
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 348783 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JHHTCP3H80K001199
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Tyre Size: F: 215/75R17.5 G Traction
 R: 7.00 R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Triangle
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6/6 mm
 L/Bal. 6 mm L/Bal. 6/6 mm
 D.O.A. 14/03/23 D.O.I. 16/3/23
 Survey held at _____

Bal. or Market Value: \$40k.
 IDAC Accident Rpt: Consistent?: Yes or No
 GIA / PR Seen: Consistent?: Yes or No
 Est. Repairs: 8 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS 3 2956
 Date: _____ Person Contacted: 274817520
 Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
N/S Rnd & Rnd w/sreen cracked
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Rep 10k.
@ 9am cor until 07-03-2027

4/4/23 2/5 @ 10,000 internal heavy (red @ 8495.09, 46%)

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Date/Time, File Return to?
 Days Of Repair: 8
 Resurvey No. of Trip: 2 Survey Fee: _____
 Transportation: _____
 Add Fee: : Site Insp (\$) _____ S + RS, _____ SI
 : Interview (\$) Photos
 : Tech. Invs (\$) Others
 : Weekend (\$) _____
 Report Format : MER-TP
 Lump Sum / I.B.I.: (\$ 10000)
 TOTAL _____

BLUWEL AUTOMOTIVE SERVICE PTE LTD
 1 KAKI BUKIT AVE 6 # 01-28/53/55/56
 SINGAPORE 417883 TEL :67452088

not allowed
du
16/3/23
2/3 @ 10,000/
8 days

VEHICLE No: YN 2936S

1PC	FRONT WINDSCREEN	<i>CNE</i>	\$1,265.00	<i>✓</i>
1PC	FRONT WINDSCREEN RUBBER	<i>all</i>	\$268.00	<i>✓</i>
1PC	FRONT PANEL	<i>Body ID</i>	\$1,324.70	<i>✓</i>
1PC	FRONT GRILLE	<i>CNE</i>	\$1,045.00	<i>✓</i>
1PC	FRONT GRILLE LOGO	<i>→ NEC</i>	\$108.00	<i>✓</i>
1PC	FRONT BUMPER	<i>DIS</i>	\$1,005.20	<i>✓</i>
1PC	FRONT BUMPER BRACKET N/S	<i>best</i>	\$342.90	<i>✓</i>
1PC	FRONT BUMPER FOG LAMP N/S	<i>CNE</i>	\$350.90	<i>✓</i>
1PC	FRONT CORNER PANEL N/S	<i>DIS</i>	\$644.70	<i>✓</i>
1PC	HEADLAMP N/S	<i>bro</i>	\$1,088.60	<i>✓</i>
1PC	HEADLAMP BULB N/S	<i>11</i>	\$10.00	<i>x</i>
1PC	FRONT DOOR N/S	<i>R</i>	\$1,915.00	<i>x</i>
1PC	FRONT DOOR SIGNAL LAMP N/S	<i>CNE</i>	\$148.00	<i>✓</i>
1PC	FRONT DOOR MIRROR BRACKET N/S	<i>bro</i>	\$420.00	<i>✓</i>
1PC	FRONT DOOR MIRROR N/S	<i>M/S</i>	\$185.00	<i>✓</i>
1PC	FRONT DOOR MIRROR ROUND N/S	<i>M/S</i>	\$125.00	<i>✓</i>
1PC	FRONT DOOR OUTER PILLAR N/S	<i>Body ID</i>	\$989.00	<i>✓</i>
1PC	FRONT DOOR INNER PILLAR N/S	<i>R</i>	\$866.00	<i>x</i>
2PCS	FRONT DOOR HINGES @\$145.00	<i>11</i>	\$290.00	<i>x</i>
1PC	FRONT DOOR CHECKER N/S	<i>11</i>	\$162.00	<i>x</i>
1PC	FRONT DOOR INNER LOCK N/S	<i>11</i>	\$350.00	<i>x</i>
1PC	FRONT DOOR INNER RUBBER N/S	<i>11</i>	\$291.00	<i>x</i>
1PC	FRONT WHEEL ARCH APNEL N/S	<i>R</i>	\$545.00	<i>x</i>
1PC	FRONT STEP PANEL N/S	<i>R</i>	\$366.00	<i>x</i>
1PC	FEONT STEP PANEL GARNISH N/S	<i>DIS</i>	\$305.00	<i>✓</i>
1PC	FRONT STEP PANEL GARNISH LAMP N/S	<i>11</i>	\$105.00	<i>x</i>
1PC	FRONT CONDENSER	<i>put</i>	\$1,133.00	<i>✓</i>
1PC	FRONT CONDENDER BRACKET	<i>R</i>	\$302.10	<i>x</i>
			\$15,950.10	
			LESS 10%	\$14,355.09

S.NETT

1SET	FRONT BUMPER CLIPS	<i>all</i>	\$50.00	<i>40</i>
1PC	FRONT WINDSCREEN SEALANT	<i>all</i>	\$50.00	<i>40</i>
1SET	FRONT DOOR INNER TRIM BOARD CLIPS	<i>11</i>	\$50.00	<i>x</i>
	TO CHECK WIRING		\$50.00	<i>20</i>
	TO DISMANTLE & REPLACED FRONT WINDSCREEN		\$120.00	<i>100</i>
	TO DISMANTLE & REFIX DASHBOARD		\$380.00	<i>250</i>
	TO DISMANTLE & REFIX FRONT DOOR MECHANISM		\$120.00	<i>x</i>
	TO REFILL AIR CON GAS	<i>11</i>	\$120.00	<i>100</i>
	TO SPRAY RUST PROOFING		\$100.00	<i>80</i>

TO CONDUCT WHEEL ALIGNMENT
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

ur \$100.00 X
\$1,500.00 1200
\$1,500.00 1000
TOTAL \$18,495.09

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-10748
102
9673.2
80
2750
125032
202
10002