

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

HODOLIES (CINOADORS) DES LED		
HSBC LIFE (SINGAPORE) PTE LTD Ref: CS3/F	HSB23002718/Kqp3e2	
10 MARINA BOULEVARD Date: 20/03/ #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983	/2023	
ATTN: OH VALE Code: HSB		
1. Policy Particulars :- (THIRD PARTY CLAIM)		
Insured Veh. SHD 896R Veh. Inspected SJV 6	8825M	
Policy No. VFX/P2413997 Coverage (\$) 0.00		
Claim No. S3M04HGT Excess (\$) 0.00		
Assign From OH VALE Assign Date 15/03/	/2023	
2. Vehicle Particulars & Condition		
Make & Model TOYOTA CAMRY (A) c.c 1998		
Engine No. HIDDEN Year of Reg. 2010		
Chassis No. MR053BK4107055226 Colour META	ALLIC LIGHT GREEN	
Odometer 157493 KM Steering IN OF	RDER	
Brakes IN ORDER Modification SPOR	RTS RIM	
General GOOD		
3. Conditions of Tyres		
Size Make Balar	nce	
R/H Front Tyre 215/60 R16 KUMHO 5 mm		
L/H Front Tyre 215/60 R16 KUMHO 5 mm		
R/H Rear Tyre 215/60 R16 KUMHO 5 mm		
L/H Rear Tyre 215/60 R16 KUMHO 5 mm		
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.		
5. General Information		
Accident Date 02/01/2023 Inspect Date / Time 15/03/	/2023 (01:42 PM)	
Survey held at SANTEE AUTO		
Block 1019 #01-388 Yishun Industrial Park A Singapore 768761		
5a. Remarks		
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500		
5b. Estimate Days of Repair		
ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days		

Report Ref No. CS3/HSB23002718/Kqp3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser