

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

**Our File No:** CS4/MSG23002729/PQY3M4**Date:** 27/04/2023**REFERENCE**

Insured/Claimant:	CHAN WEE TEONG	Policy No:	1001884999	
Date of Loss:	11/02/2023	Nature of Claim:	OD TFR	Claim No: 304784

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>FBK2806Y</b>		
Make & Model:	SUZUKI UH200AL5 BURGMAN, 200cc ABS	Engine No:	H405402163
Reg. Date:	28/05/2015 (Man. Year: 2015)	Chassis No:	MLCC9112100402163
Colour:	Grey	Odometer:	0 km
Engine Capacity:	200 cc		
Market Value/New Car Price:	S\$3,800.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:		Rear Tyre Size:	
Front Left Side:	0 mm	Rear Left Side:	0 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>- Excess (\$\$)</b>	300.00	300.00	0.00	0.00
<b>Nett Amount (\$\$)</b>	<b>-300.00</b>	<b>-300.00</b>	<b>0.00</b>	<b>0.00</b>

**INSPECTION**

Date of Assignment:	16/03/2023		
Date Inspected:	16/03/2023	Inspected At:	Glen Enterprise Pte Ltd (HQ) 1100 / 1102 Serangoon Road Singapore 328196
Estimated Period of Repair:	0.0 days		

**Adjuster:** Sherwin Beh Swee Yang**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :	\$3,800.00
OMV :	\$4,132.00
PARF Rebate (1) :	\$ 0.00
Quota Premium Paid :	\$6,512.00
COE Rebate (2) :	\$1,396.00
Total Rebate (1) + (2) = :	\$1,396.00

The total amount incurred will be Market Value \$3,800.00 minus Total Rebate \$1,396.00 = \$2,404.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Apr 2023)	
Parts:	N/A	SUZUKI UH200AL5 BURGMAN 200cc ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK2806Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
---

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >