

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01 (Claims & Performance Management)  
Singapore 068897**Our File No:** CS6/AIS23002732/HNY3E2  
**Date:** 04/07/2023**REFERENCE**Insured/Claimant: NG TECK SENG Policy No: SP2000643955-01  
Date of Loss: 13/03/2023 Nature of Claim: OD Claim No: SKB181U-XXX**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SKB181U**  
Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A) Engine No: L15B4030318  
Reg. Date: 02/12/2016 (Man. Year: 2015) Chassis No: RU11110314  
Colour: White Odometer: 149715 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: S\$51,000.00  
Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:**CONDITION OF TYRES**Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm  
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,283.70	6,533.50	750.20	10.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,170.00	1,630.00	1,540.00	48.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,453.70</b>	<b>8,163.50</b>	<b>2,290.20</b>	<b>21.91</b>
<b>- Excess (S\$)</b>	0.00	1,100.00	-1,100.00	
<b>(S\$)</b>	10,453.70	7,063.50	3,390.20	32.43
<b>+ GST 8.00/8.00% (S\$)</b>	836.30	565.08	271.22	32.43
<b>Nett Amount (S\$)</b>	<b>11,290.00</b>	<b>7,628.58</b>	<b>3,661.42</b>	<b>32.43</b>

**INSPECTION**Date of Assignment: 16/03/2023 Present Location: Falcon-Air Auto Services Pte Ltd (Sin Ming)  
Falcon-Air Auto Services Pte Ltd (Sin Ming)  
Date Inspected: 16/03/2023 Inspected At: 176 Sin Ming Drive #01-06, Sin Ming Autocare  
Singapore 575721  
Estimated Period of Repair: 6.0 days**Adjuster:** Edward**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2023)
<b>Parts:</b> M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SKB181U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*Bonnet</b> (WCP)	Buckled	420.00 F	*420.00 F
2	1		<b>*Bonnet hinge LH</b> (WCP)	Bent	35.00 F	*35.00 F
3	1		<b>*Bonnet hinge RH</b> (WCP)	Bent	35.00 F	*35.00 F
4	1		<b>*Bonnet Lock</b> (WCP)	Not Necessary	80.00 F	*- F
5	1		<b>*Bonnet Lock Insulator Clip</b>	Necessary	40.00 FS	*40.00 FS
6	1		<b>*Radiator</b> (WCP)	Bent	780.00 F	*780.00 F
7	1		<b>*Radiator Support Panel</b> (WCP)	Broken	420.00 F	*420.00 F
8	1		<b>*Air Con Condenser</b> (WCP)	Bent	420.00 F	*420.00 F
9	1		<b>*LH Headlamp</b> (WCP)	Cracked	950.00 F	*950.00 F
10	1		<b>*LH Headlamp Lower Bracket</b> (WCP)	Broken	25.00 F	*25.00 F
11	1		<b>*Air Duct</b> (WCP)	Cracked	50.00 F	*50.00 F
12	1		<b>*Front Grille</b> (WCP)	Cracked	250.00 F	*250.00 F
13	1		<b>*Front Grille Chrome LH</b> (WCP)	Cracked	28.00 F	*28.00 F
14	1		<b>*Front Grille Chrome RH</b> (WCP)	Cracked	28.00 F	*28.00 F
15	1		<b>*Front Grille Logo</b> (WCP)	Cut	18.00 F	*18.00 F
16	1		<b>*Front Grille Holder Centre</b> (WCP)	Cracked	60.00 F	*40.00 F
17	1		<b>*Front Grille Holder Clip</b>	Necessary	40.00 FS	*40.00 FS
18	1		<b>*Front Grille Top Holder LH</b> (WCP)	Cracked	18.00 F	*18.00 F
19	1		<b>*RH Headlamp Lower Bracket</b> (WCP)	Broken	25.00 F	*25.00 F
20	1		<b>*RH Headlamp</b> (WCP)	Cracked	950.00 F	*950.00 F
21	1		<b>*Horn</b> (WCP)	Serviceable	45.00 F	*- F
22	1		<b>*Front Bumper</b> (WCP)	Distorted	200.00 F	*200.00 F
23	1		<b>*Front Bumper Reinforcement</b> (WCP)	Bent	185.00 F	*185.00 F
24	1		<b>*Front Bumper Side Bracket LH</b> (WCP)	Distorted	14.00 F	*14.00 F
25	1		<b>*Front Bumper Side Bracket RH</b> (WCP)	Distorted	14.00 F	*14.00 F
26	1		<b>*Front Bumper Lower Black</b> (WCP)	Cracked	148.00 F	*140.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
27	1		<b>*Front Bumper Lower Grille</b> (WCP)	Cracked	60.00 F	*60.00 F
28	1		<b>*Front Bumper Clip</b>	Necessary	60.00 FS	*60.00 FS
29	1		<b>*Front Grille Bracket</b> (WCP)	Broken	165.00 F	*165.00 F
30	1		<b>*Fog Lamp Garnish LH</b> (WCP)	Cracked	22.00 F	*22.00 F
31	1		<b>*Fog Lamp LH</b> (WCP)	Cracked	145.00 F	*145.00 F
32	1		<b>*Air Guide LH</b> (WCP)	Not Necessary	50.00 F	*- F
33	1		<b>*Front Fender Shield LH</b> (WCP)	Torn	85.00 F	*85.00 F
34	1		<b>*Front Fender Shield Clip</b>	Necessary	40.00 FS	*40.00 FS
35	1		<b>*Air Resonator Box</b> (WCP)	Cracked	98.00 F	*98.00 F
36	1		<b>*Front Number Plate</b>	Cracked	45.00 FS	*45.00 FS
37	1		<b>*Front Engine Undercover</b> (WCP)	Broken	100.00 F	*100.00 F
38	1		<b>*LH Front Fender</b> (WCP)	Repair	200.00 F	*- F
<b>Supplementary #1</b>						
39	1		<b>*LH FOG LAMP BRACKET</b> (WCP)	Broken	15.00 F	*15.00 F

F=Franchise part. S=SpcNett.

<b>Sub Total (\$\$)</b>	<b>6,363.00</b>	<b>5,960.00</b>
<b>+ Margin on L,N Items 15.00/10.00% (\$\$)</b>	920.70	573.50
<b>Total Parts (\$\$)</b>	<b>7,283.70</b>	<b>6,533.50</b>

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	To check wiring and light system	New	50.00	30.00
2	To vacuum, reoil and recharge air con gas	New	120.00	100.00
3	To cut out, reweld radiator support panel, straighten RH front fender, front chasis, wheel house including replacement of parts	New	1,200.00	600.00
4	To spray paint bonnet, bonnet hinges, front chassis, front bumper, radiator support panel, LH/RH front fender, wheel house, RH front door	New	1,800.00	900.00
			<b>Gross Labour Cost (\$\$)</b>	<b>3,170.00</b>
				<b>1,630.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >