

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG23002734/UPA3Q2**Date:** 05/07/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220149926
<b>Claimant Vehicle No :</b>	GBK9653A	<b>Insured Vehicle No :</b>	SND5970E
Date of Loss:	14/03/2023	Nature of Claim:	TP
		Claim No:	2922390926SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBK9653A</b>		
Make & Model:	TOYOTA HIACE, 2.8 D DX (A)	Engine No:	1GD8654080
Reg. Date:	27/01/2021 (Man. Year: 2020)	Chassis No:	GDH2012016011
Colour:	White	Odometer:	55461 km
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,930.78	1,407.66	6,523.12	82.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,390.00	2,110.00	2,280.00	51.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,320.78</b>	<b>3,517.66</b>	<b>8,803.12</b>	<b>71.45</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,320.78</b>	<b>2,800.00</b>	<b>9,520.78</b>	<b>77.27</b>
<b>+ Loss of Use (5.0 x S\$90.00/day) (S\$)</b>		450.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,252.00</b>		

INSPECTION

Date of Assignment:	16/03/2023	
Date Inspected:	16/03/2023	Inspected At: Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838
Estimated Period of Repair:	5.0 days	

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S DOOR	Repair	2,038.90 F	*- FL
2	20		*FRONT O/S DOOR INNER TRIM BOARD CLIPS	Not Necessary	70.00 F	*- FL
3	1		*FRONT O/S DOOR COMPANY STICKER	Necessary	60.00 F	*60.00 FL
4	1		*FRONT O/S DOOR LOCK PILLAR PANEL	Dented	444.98 F	*444.98 FL
5	1		*O/S SIDE DOOR	Repair	2,069.20 F	*- FL
6	20		*O/S SIDE DOOR INNER TRIM BOARD CLIPS	Not Necessary	90.00 F	*- FL
7	1		*REAR O/S FENDER	Repair	1,675.80 F	*- FL
8	20		*REAR O/S FENDER INNER TRIM BOARD CLIPS	Not Necessary	110.00 F	*- FL
9	1		*FRONT & REAR O/S WHEEL HUPCAP	Cut	459.40 F	*459.40 FL
10	1		*FRONT STEP GARNISH O/S	Cut	231.40 F	*231.40 FL
11	1		*REAR BUMPER	Cut	681.10 F	*681.10 FL
					Sub Total (S\$)	7,930.78 1,876.88
					- List Item Discount on L Items 0.00/25.00% (S\$)	0.00 469.22
					Total Parts (S\$)	7,930.78 1,407.66

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	60.00	20.00
2	TO CHECK & ADJUST FRONT & REAR WHEEL ALIGNMENT & BALANCING	New	180.00	60.00
3	TO REMOVE & REFIX FRONT DOOR INNER TRIM BOARD ,GLASS ,CHANNEL ,REGULATOR ,INNER LOCK ,WEATHERSTRIP HINGE ,MOLDING ,GARNISH & NECESSARY PARTS ,INTO NEW DOOR	New	180.00	0.00
4	TO REMOVE & REFIX FRONT CUSHION SEAT ,CARPET FLOOR MAT ,GARNISH,SIDE DOOR TRIM BOARD ,REAR O/S FENDER TRIM BOARD & NECESSARY PARTS ,TO ENABLE REPAIR O/S DOOR ,REAR O/S FENDER ,O/S DOOR LOCK PILLAR PANEL & NECESSARY PARTS	New	250.00	0.00
5	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	120.00	50.00
6	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK ,STRAIGHTEN & KNOCKING OUT O/S DOOR LOCK PILLAR PANEL ,REAR O/S FENDER & NECESSARY PARTS ,TO WELD ,RENEW & ALIGN ABOVE PARTS	New	1,800.00	900.00
7	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,800.00	1,080.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,390.00</b>	<b>2,110.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >