

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CC 6/Alt 23002734/Upa3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

GIA / PR Seen: _____

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Date / Time

Action / Instruction

Dep 11k

Veh No: _____

Yr Regn: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Colour: _____

Sp. Reading: _____

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

Rear

R/Bal. _____

mm

L/Bal. _____

mm

D.O.I. _____

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee: _____

Transportation: _____

) S + RS, SI

) Photos

) Others

TOTAL

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 3104/03/23

Your Ref:

M/S H. M. CURTAIN PTE. LTD.
BLK 211, #01-747
NEW UPPER CHANGI RD,
SINGAPORE 460211

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date: 16th March 2023

2-1876.88
252
1407.60
2110

Estimate cost of repair to TOYOTA HIACE VAN - GBK 9653 A

1 pc front o/s door	R	\$ 2,038.90	q
20 pcs front o/s door inner trim board clips	11	70.00	q
1 pc front o/s door company sticker	2er	60.00	—
1 pc front o/s door lock pillar panel	20	444.98	—
1 pc o/s side door	R	2,069.20	q
20 pcs o/s side door inner trim board clips	11	90.00	q
1 pc rear o/s fender	R	1,675.80	q
20 pcs rear o/s fender inner trim board clips	11	110.00	q
2 pcs front & rear o/s wheel hupcap	Cu7	459.40	—

1 pc front step garnish o/s \$231.40 Cu7 ✓
1 pc Rear bumper \$681.10 Cu7 ✓

To wiring check up for affected wiring system. 60.00 20

To check & adjust front & rear wheel alignment & balancing. 180.00 60

To remove & refix front door inner trim board, glass, channel, regulator, inner lock, weatherstrip, hinge, moulding, garnish & necessary parts, into new door. 11 180.00 X

To remove & refix front cushion seat, carpet, floor mat, garnish, side door trim board, rear o/s fender trim board & necessary parts, to enable repair o/s door, rear o/s fender & o/s door lock pillar panel & necessary parts. 11 250.00 X

To respray Tuff-Kote on all affected accident parts. 120.00 50

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out o/s door lock pillar panel, rear o/s fender & necessary parts, to weld, renew & align above parts. 1,800.00 900

To putty & respray painting on all affected accident parts, 1,800.00 1000