

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002738/AQP3E2**Date:** 16/05/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00089582201

**Claimant Vehicle
No :** GBH5246J**Insured Vehicle
No :** SLN8501C

Date of Loss: 13/03/2023

Nature of Claim: TP

Claim
No: SNM23D201961/C03/LEWLCDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBH5246J**

Make & Model: NISSAN NV350, 2.5 D Panel Van (M)

Engine No: YD25425129A

Reg. Date: 30/06/2018 (Man. Year: 2017)

Chassis No: JN1MC2E26Z0008953

Colour: White

Odometer: 125833 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 195 R15C

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,402.99	11,285.46	8,117.53	41.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,690.00	3,190.00	2,500.00	43.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,092.99	14,475.46	10,617.53	42.31
Approved Total (Overridden) (S\$)		11,500.00		
Nett Amount (S\$)	25,092.99	11,500.00	13,592.99	54.17

INSPECTION

Date of Assignment: 16/03/2023

Date Inspected: 16/03/2023 Inspected At:

AUTO UNITED SG PTE LTD (HQ)
13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ
CENTRE
Singapore 417807

Estimated Period of Repair: 11.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 May 2023)	
Parts:	N/A	NISSAN NV350 2.5 D Panel Van (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH5246J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	678.40 FL	*678.40 FL
2	2		*FRONT BUMPER SIDE HOLDER	Damaged	310.20 FL	*310.20 FL
3	1		*FRONT BUMPER REINFORCEMENT	Dented	528.70 FL	*528.70 FL
4	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	105.80 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP	N/S Cracked	623.60 FL	*311.80 FL
6	1		*FRONT BUMPER FOG LAMP COVER	N/S Deformed	260.20 FL	*130.10 FL
7	1		*FRONT GRILLE	Cracked	479.30 FL	*479.30 FL
8	1		*FRONT GRILLE LOGO	Necessary	65.00 FL	*65.00 FL
9	2		*HEADLAMP	Cracked	970.60 FL	*970.60 FL
10	2		*FRONT CORNER PANEL	Not Necessary	1,071.00 FL	*- FL
11	1		*FRONT STEP PANEL	N/S Distorted	281.80 FL	*140.90 FL
12	2		*FRONT STEP PANEL GARNISH	Deformed	480.80 FL	*480.80 FL
13	2		*FRONT DOOR	Distorted	2,447.80 FL	*2,447.80 FL
14	2		*FRONT DOOR LOCK	Not Necessary	420.80 FL	*- FL
15	1		*FRONT DOOR WEATHERSTRIPE	N/S Cut	335.60 FL	*167.80 FL
16	1		*FRONT DOOR LOWER RUBBER	N/S Cut	125.00 FL	*62.50 FL
17	2		*FRONT DOOR INNER TRIM BOARD	Cracked	1,009.20 FL	*1,009.20 FL
18	1		*FRONT DOOR REGULATOR MOTOR	N/S Damaged	538.40 FL	*269.20 FL
19	1		*FRONT DOOR REGULATOR GEAR	N/S Damaged	374.80 FL	*187.40 FL
20	1		*FRONT LH DOOR WING MIRROR	Not Necessary	553.90 FL	*- FL
21	1		*FRONT LH DOOR OUTER HANDLE	Not Necessary	149.40 FL	*- FL
22	1		*FRONT LH DOOR OUTER PILLAR	Distorted	1,157.10 FL	*1,157.10 FL
23	1		*FRONT LH DOOR INNER PILLAR	Repair	841.40 FL	*- FL
24	1		*FRONT LH WHEEL ARC PANEL	Buckled	696.40 FL	*696.40 FL
25	1		*FRONT LH WHEEL ARC PANEL GARNISH	Deformed	195.50 FL	*195.50 FL
26	1		*FRONT LH WHEEL ARC PANEL RUBBER	Cut	58.60 FL	*58.60 FL
27	1		*WIPER WASHER TANK	Not Necessary	129.60 FL	*- FL
28	1		*FRONT WINDSCREEN MOULDING	Not Necessary	213.30 FL	*- FL
29	1		*FRONT LOWER ARM	N/S Bent	457.40 FL	*228.70 FL
30	1		*FRONT SHOCK ABSORBER	N/S Damaged	450.20 FL	*225.10 FL
31	1		*FRONT KNUCKLE ARM	N/S Damaged	770.40 FL	*385.20 FL
32	2		*FRONT UPPER ARM	Not Necessary	690.80 FL	*- FL
33	1		*FRONT WHEEL HUB C/W BEARING	N/S Damaged	906.20 FL	*453.10 FL
34	1		*DASHBOARD	Not Necessary	1,103.90 FL	*- FL
35	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
36	1		*FRONT GRILLE CLIPS	Not Necessary	20.00 FS	*- FS
37	1		*FRONT DOOR INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*60.00 FS
38	1		*FRONT DOOR SPEAKER	N/S Cracked	400.00 FS	*150.00 FS
39	1		*FRONT RH DOOR COMPANY ADDRESS STICKER	Necessary	30.00 FS	*30.00 FS
40	1		*FRONT LH WHEEL ARC GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
41	1		*FRONT WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
42	1		*FRONT WHEEL RIM	N/S Cut	500.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

5/16/23, 2:11 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	2		*FRONT WHEEL RIM COVER	N/S Missing / O/S Cut	300.00 FS	*160.00 FS
44	1		*FRONT TYRE	N/S Cut	440.00 FS	*160.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					21,351.10	12,449.40
- List Item Discount on L Items 10.00/10.00% (\$\$)					1,948.11	1,163.94
Total Parts (\$\$)					19,402.99	11,285.46
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	1,400.00
2	SPRAY PAINTING	New	1,600.00	1,100.00
3	WIRING	New	100.00	30.00
4	TO APPLY TUFF COAT	New	150.00	80.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO TRANSFER LH & RH DOOR FITTINGS	New	300.00	160.00
7	TO REMOVE DASHBOARD	New	350.00	0.00
8	TO REMOVE FRONT WINDSCREEN	New	180.00	0.00
9	TO REMOVE FRONT PASSENGER SEAT	New	200.00	0.00
10	TO DISMANTLE FRONT LH & RH UNDERCARRIAGES	New	650.00	220.00
11	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
12	TOWING FEES	New	60.00	60.00
Gross Labour Cost (\$\$)			5,690.00	3,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >