Motor Vehicle Appraiser and Insurance Loss Adjuster No. 10 Kaki Bukit Ave 4 #06-75 Premier @ Kaki Bukit Singaore 415874 Handphone No.: +65 9146 1186 Email: united.appraisal@live.com.sg Business Registration Nos.: 200817301N

INVOICE

To : Mohamed Noor Bin Mohamed Hanifa Date

: 04 Mar 2022

: LKT Group Pte Ltd c/o

Blk 3006 Ubi Rd 1

Invoice No. : 8094123

#01-384

Singapore 408700

DESCRIPTION	AMOUNT
Service rendered for appraisal / inspection report :	
Professional inspection fees	SGD 563.00
Photographs 23 pcs	
Transport fees	
Re-inspection fees (work in progress, post repair inspection)	
Total	SGD 563.00
Singapore dollar: FIVE HUNDRED SIXTY THREE ONLY.	
Registration no. : FBH800S	
Make/Model : Kawasaki KR150K	
Our reference : UAM21.07.32-AK-STP-LKT-FBH800S	
All payments made payee to:-	
" UNITED APPRAISAL & MANAGEMENT PTE LTD"	



Motor Vehicle Appraiser and Insurance Loss Adjuster No. 10 Kaki Bukit Ave 4 #06-75 Premier @ Kaki Bukit Singaore 415874 Handphone No.: +65 9146 1186 Email: united.appraisal@live.com.sg Business Registration Nos.: 200817301N

Our ref.: UAM21.07.32-AK-STP-LKT-FBH800S

: 04 Mar 2022

Mohamed Noor Bin Mohamed Hanifa

WITHOUT PREJUDICE
Dear Sir,
Re: Third Party Claim For Vehicle Registration No. FBH800S
We refer to your instruction to appraise the above-mentioned vehicle on 27 September 2021
A static inspection was carried out and our report is enclosed for your perusal. The estimated cost of repair submitted by Messrs. LKT Group Pte Ltd for SGD 13,703.36 as per our attached schedule has been inspected thoroughly by us against the actual damages sustained on the above-mentioned vehicle and we recommend the replacement and rectification accordingly.
Our revised quotation for the repair is SGD 12,217.02. In our opinion, it to be excessive. Therefore, we recommend a contract lump-sum repair cost. This is more economical than to have the above-mentioned vehicle repaired on parts by/for parts basis. Invariably, the repairer has the prerogative/option for the recommended replacement parts to either be repaired or be replaced.
We have negotiated with the repairer and they have agreed to repair the above-mentioned vehicle for SGD 9,750.00 NETT. Which, in our opinion is fair and reasonable.
The repairer has agreed to undertake the repairs to your requirement at the recommended contract lump-sum. However, we have not given any instruction and authorisation to the repairer to proceed with the repairs.
Under normal circumstances, the entire repair of the damaged vehicle should be completed within a reasonable period of 9 (Nine) days.
We are reverting the matter to you for a decision, and enclosed is our vehicle inspection report, appraisement schedule and invoice for services rendered.
Please do not hesitate to contact us if you have any queries on this matter.
Yours faithfully, United Appraisar & Management Pte Ltd
Ananda K. Biswas Marc Motor Vehicle Appraiser
Encls.:

The information contained in these document may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you received this document by error, please contact us immediately to arrange for its return.

VEHICLE INSPECTION REPORT

To: Mohamed Noor Bin Mohamed Hanifa

Our ref.: UAM21.07.32-AK-STP-LKT-FBH800S

Date : 04 Mar 2022

REFERENCE

: To be advice : Mohamed Noor Bin Mohamed Hanifa Insured Assign by : To be advice Policy no. : 27 Sep 2021 Assign on : To be advice : 27 Sep 2021 Claim no. Inspection on Sum insured : To be advice Accident on : 22 Sep 2020 Workshop name: LKT Group Pte Ltd : Not applicable Excess : To be advice : Blk 3006 Ubi Rd 1 Inspection at 3rd party Veh. #01-384 : To be advice 3rd party ins.

Singapore 408700

PARTICULARS OF DAMAGED VEHICLE

Registration no. : FBH800S Odometer : 32824 km

Make / Model : Kawasaki KR150K Chassis no. : KR150KA57234

Regn. date : 02 Sep 2003 Engine no. : KR150EEA57234

Body colour : Black Engine cap. : 148 cc

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

Steering : In order Paintwork : Good
Footbrake : In order Undercarriage : Serviceable
Handbrake : In order Gen. condition : Good

TYRE CONDITION ON VEHICLE


		Make	Size	Tread depth	Type of road wheel
Front N/S	:	Pirelli	90/80-17M	70%*	Alloy*
Front O/S	:	N/A	N/A	70%	N/A
Rear N/S	:	Pirelli	100/90-17M	70%*	Alloy*
Rear O/S	:	N/A	N/A	70%	N/A

NOTE: The above percentages represent the estimated remaining life of tyre threads.

^{*} Denotes damaged component/s

POINT OF IMPACT

On the front in the direction from right to left.



SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT

The impact of the collision has damaged / affected the front and rear wheel, front fender, front fork, handle bar, fuel tank, fairing, seat, gear pedal, rear brake pedal, footrest, headlight, taillight, chassis frame and etc...

Please refer to Annex A (Appraisement Schedule) for a detailed account of the damages and photographs taken.

Note: Reinspection vehicle on xx abc 2021 for repair in progress.

RECOMMENDATION

The estimate cost of repair submitted by Messrs

LKT Group Pte Ltd

as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. We have not authorised the repairs.

Our adjusted cost of repair is SGD 9,750.00 to carry out the repairs. Please refer to Annex A (Appraisement Schedule) for a detailed account of the cost estimates.

REMARKS

We have not authorised the repair. However, for information, under normal circumstances, the repair would takes approximately **9 (Nine)** working days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** the repair to the damaged vehicle and the survey was conducted strictly on a "WITHOUT PREJUDICE" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report, which includes evidence photographs.

Yours faithfully, United Appraisal & Management Pte Ltd



Ananda K. Biswas Marc Motor Vehicle Appraiser

APPRAISEMENT SCHEDULE

Annex A

Registration no. : FBH800S

Our reference

: UAM21.07.32-AK-STP-LKT-FBH800S

S/N	Qty	Description	Condition /	Estimate by Wshop SGD	Adjusted
			Remarks	Wallop SGD	Amt SGD
		<u>LIST ITEMS</u>			
1	1	Front windshield	Missing	180.55	180.55
2	1	Front fairing	Missing	398.00	398.00
3	1	Front fairing inner cover	Missing	96.20	96.20
4	1	Front fairing inner bracket	Bend	179.88	179.88
5	2	Side fairing centre @ SGD 205.00	Missing	410.00	410.00
6	1	Side fairing lower @ SGD 196.00	Missing	392.00	392.00
7	1	Rear side fairing @ SGD 193.40	Grazed	386.80	386.80
8	1	Front fender	Cracked	98.12	98.12
9	1 pair	Side mirror	Missing	90.00	90.00
10	1	Headlight	Missing	685.90	685.90
11	1	Headlight stay	Missing	220.00	220.00
12	1	Speedometer	Cracked	455.32	455.32
13	1	Speedometer cable	Snap	187.60	187.60
14	2	Front signal lamp @ SGD 38.00	Missing	76.00	76.00
15	2	Rear signal lamp @ SGD 38.00	Cracked	76.00	76.00
16	1	Handle bar	Bend	129.20	129.20
17	1 set	Handle grip	Cut	67.56	67.56
18	1 set	Handle balancer	Grazed	48.00	48.00
19	1	Front brake master cylinder pump	Damaged	145.22	145.22
20	1	Front brake fluid reservoir	Damaged	136.89	136.89
21	1	Front brake lever	Bend	58.00	58.00
22	1	Front brake caliper	Jammed	287.00	287.00
23	1	Front rim shaft	Bend	28.15	28.15
24	1	Front wheel bearing	Necessary	28.15	28.15
25	1	Clutch lever	Bend	58.00	58.00
26	1	Clutch cable	Jammed	92.60	92.60
27	1	Steering spindle	Distorted	182.55	182.55
28	1	Steering stem	Distorted	190.75	190.75
29	2	Front fork inner tube @ SGD 220.00	Bend	440.00	440.00
30	2	Front fork outer tube @ SGD 140.00	Bend	280.00	280.00
31	1	Front fork top clamp	Distorted	169.00	169.00
32	1	Front fork under bracket	Distorted	148.30	148.30
33	2	Front footrest @ SGD 50.00	Snapped	100.00	100.00
34	2	Front footrest bracket @ SGD 90.00	Distorted	180.00	180.00
35	1	Gear pedal	Bend	145.00	145.00
36	1	Fuel tank	Dented	450.00	450.00
37	2	Air intake duct @ SGD 130.00	Cracked	260.00	260.00
38	2	Rear side board @ SGD 170.00	Cracked	340.00	340.00
39	1	Rear swing arm	Distorted	420.00	420.00
40	1	Rear rim shaft	Bend	34.50	34.50
41	1	Rear wheel bearing	Necessary	35.00	35.00
42	2	Rear footrest @ SGD 45.00	Snapped	90.00	90.00
43	2	Rear footrest bracket @ SGD 120.00	Distorted	240.00	240.00
44	1	Rear mudguard	Re-Used	85.00	0.00

APPRAISEMENT SCHEDULE

Annex A

Registration no. : FBH800S

Our reference

: UAM21.07.32-AK-STP-LKT-FBH800S

Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 13703.36 12217.02 127.02	S/N	Qty	Description	Condition /	Estimate by	Adjusted	
Total Parts and Labour Cost of Repair Toral 118.20 118.20 118.20 118.20 118.20 118.20 118.20 121.60		~·3		Remarks	Wshop SGD	Amt SGD	
1 Rear seat assy	45	1	Taillamp	Cracked	290.00	290.00	
1			-	Torn	118.20	118.20	
1				Cracked	236.42	236.42	
Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) Cut 25.00 26.33 25.00 25.00 26.33 25.00		1	Radiator fluid reservoir tank	Missing	121.60	121.60	
Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) Sciool 25.00 Sciool	49	1	Radiator hose top	Cut	50.00	50.00	
Chassis frame	50	1	Radiator hose bottom	Cut	25.00	25.00	
Less 0%/10% 9698.36 9613.36 Less 0%/10% 0.00 961.34 9698.36 8652.02 SPECIAL NETT ITEMS 1 1 Sundries Necessary 50.00 30.00 2 1 Body sticker Necessary 90.00 90.00 3 1 Fork oil Necessary 40.00 40.00 4 1 Fork oil seal Necessary 50.00 50.00 5 1 Front number plate Bend 70.00 50.00 6 1 IU unit Shorted 180.00 180.00 7 1 IU bracket Twisted 25.00 25.00 8 1 Exhuast pipe Bend 780.00 780.00 9 1 Front alloy rim R17 Cracked 320.00 320.00 10 1 Front tyre R17 Cut 150.00 130.00 11 1 Rear alloy rim R17 Wobbled 320.00 320.00 12 1 Rear tyre R17 Abraided 160.00 140.00 1755.00 1695.00 TOTAL 11453.36 10347.02 LABOUR & MISC CHARGES 1 To respray replaced & affected parts. 1200.00 900.00 TOTAL Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 2467.02	51	1	Horn	Malfunction	55.90	55.90	
Less 0% / 10% 9698.36 8652.02	52	1	Chassis frame	Refer To Labour	0.00		
SPECIAL NETT ITEMS SPECIAL NETT ITEMS					9698.36	9613.36	
SPECIAL NETT ITEMS				Less 0% / 10%			
1 1 Sundries Necessary 50.00 30.00 2 1 Body sticker Necessary 90.00 90.00 3 1 Fork oil Necessary 40.00 40.00 4 1 Fork oil seal Necessary 50.00 50.00 5 1 Front number plate Bend 70.00 50.00 6 1 IU unit Shorted 180.00 180.00 7 1 IU bracket Twisted 25.00 25.00 8 1 Exhuast pipe Bend 780.00 780.00 9 1 Front alloy rim R17 Cracked 320.00 320.00 10 1 Front tyre R17 Cut 150.00 130.00 11 1 Rear alloy rim R17 Wobbled 320.00 320.00 12 1 Rear tyre R17 Abraided 160.00 140.00 1755.00 1695.00 2 To remove/replace damaged parts & components 700.00 650.00 3 To respray replaced & affected parts 1200.00 900.00 TOTAL Total Parts and Labour Cost of Repair 13703.36 12217.02 Less (Lumpsum repair adjustment) 2467.02			SDECIAL NETTITEMS		9698.36	8652.02	
2			SPECIAL NETT TIEWS				
1 Fork oil Necessary 40.00 40.00 40.00 40.00 40.00 40.00 40.00 5	1	1	Sundries	Necessary	50.00	30.00	
1 Fork oil seal Necessary 50.00 50.00 5 1 Front number plate Bend 70.00 50.00 6 1 IU unit Shorted 180.00 180.00 7 1 IU bracket Twisted 25.00 25.00 8 1 Exhuast pipe Bend 780.00 780.00 9 1 Front alloy rim R17 Cracked 320.00 320.00 10 1 Front tyre R17 Cut 150.00 130.00 11 1 Rear alloy rim R17 Wobbled 320.00 320.00 12 1 Rear tyre R17 Abraided 160.00 140.00 1755.00 1695.00 1 To carry out body frame alignment 350.00 320.00 2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 2467.02 1 Total Parts and Labour Cost of Repair 13703.36 12217.02 2467.02 2467.02 2467.02 2467.02 1 Total Parts and Labour Cost of Repair 2467.02 1 Total Parts and Labour Cost of Repair 2467.02 2 Total Parts and Labour Cost of Repair 2467.02 2 Total Parts and Labour Cost of Repair 2467.02 3 Total Parts and Labour Cost of Repair 2467.02 4 Total Parts and Labour Cost of Repair 2467.02 5 Total Parts and Labour Cost of Repair 2467.02 6 Total Parts and Labour Cost of Repair 2467.02 7 Total Parts and Labour Cost of Repair 2467.02 7 Total Parts and Labour Cost of Repair 2467.02 7 Total Parts and Labour Cost of Repair 2467.02 7 Total Parts and Labour Cost of Repair 2467.02 7 Total Parts and Labour Cost of Repair 2467.02 7 Total Parts and Labour Cost of Repair 2467.02 7 Total Parts and Labour Cost of Repair 2467.02 7 Total Parts and Labour Cost of Repair 2467.02 8 Total Parts and Labour Cost of Repair 2467.02 7 Total Parts and Labour Cost of Repair 2467.02 7 Total Parts and Labour Cost of Repair 2467.02 7 Total Parts and Labour Cost of Repair 2467.02 7 Total Parts and Labour Co	2	1	Body sticker	Necessary	90.00		
5 1 Front number plate Bend 70.00 50.00 6 1 IU unit Shorted 180.00 180.00 7 1 IU bracket Twisted 25.00 25.00 8 1 Exhuast pipe Bend 780.00 780.00 9 1 Front alloy rim R17 Cracked 320.00 320.00 10 1 Front tyre R17 Cut 150.00 130.00 11 1 Rear alloy rim R17 Wobbled 320.00 320.00 12 1 Rear tyre R17 Abraided 160.00 140.00 12 1 Rear tyre R17 Abraided 1650.00 1695.00 TOTAL 11453.36 10347.02 LABOUR & MISC CHARGES 1 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL 2250.00 1870.00 <td co<="" td=""><td>3</td><td>1</td><td>Fork oil</td><td>Necessary</td><td></td><td></td></td>	<td>3</td> <td>1</td> <td>Fork oil</td> <td>Necessary</td> <td></td> <td></td>	3	1	Fork oil	Necessary		
6 1 IU unit Shorted 180.00 180.00 7 1 IU bracket Twisted 25.00 25.00 8 1 Exhuast pipe Bend 780.00 780.00 9 1 Front alloy rim R17 Cracked 320.00 320.00 10 1 Front tyre R17 Cut 150.00 130.00 11 1 Rear alloy rim R17 Wobbled 320.00 320.00 12 1 Rear tyre R17 Abraided 160.00 140.00 TOTAL 11453.36 10347.02 LABOUR & MISC CHARGES 1 To carry out body frame alignment 350.00 320.00 2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL 2250.00 1870.00 Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 13703.36 12217.02	4	1	Fork oil seal	_			
7 1 IU bracket Twisted 25.00 25.00 8 1 Exhuast pipe Bend 780.00 780.00 9 1 Front alloy rim R17 Cracked 320.00 320.00 10 1 Front tyre R17 Cut 150.00 130.00 11 1 Rear alloy rim R17 Wobbled 320.00 320.00 12 1 Rear tyre R17 Abraided 160.00 140.00 TOTAL 11453.36 10347.02 LABOUR & MISC CHARGES 1 To carry out body frame alignment 350.00 320.00 2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL 2250.00 1870.00 Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 13703.36 12217.02	5	1	Front number plate				
8 1 Exhuast pipe Bend 780.00 780.00 9 1 Front alloy rim R17 Cracked 320.00 320.00 10 1 Front tyre R17 Cut 150.00 130.00 11 1 Rear alloy rim R17 Wobbled 320.00 320.00 12 1 Rear tyre R17 Abraided 160.00 140.00 TOTAL 11453.36 10347.02 LABOUR & MISC CHARGES 1 To carry out body frame alignment 350.00 320.00 2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL 2250.00 1870.00 Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 13703.36 12217.02	6	1	IU unit	Shorted			
9 1 Front alloy rim R17 Cracked 320.00 320.00 10 1 Front tyre R17 Cut 150.00 130.00 11 1 Rear alloy rim R17 Wobbled 320.00 320.00 12 1 Rear tyre R17 Abraided 160.00 140.00 TOTAL 11453.36 10347.02 LABOUR & MISC CHARGES 1 To carry out body frame alignment 350.00 320.00 2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL 2250.00 1870.00 Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 13703.36 12217.02	7	1	IU bracket	Twisted			
10	8	1	Exhuast pipe				
11 1 Rear alloy rim R17 Wobbled Abraided 320.00 320.00 140.00 140.00 1755.00 1695.00 1755.00 1695.00 TOTAL 11453.36 10347.02 LABOUR & MISC CHARGES 1 To carry out body frame alignment 350.00 320.00 320.00 2 To remove/replace damaged parts & components. 700.00 650.00 900.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL 2250.00 1870.00 Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 13703.36 12217.02 2467.02	9	1	Front alloy rim R17				
12 1 Rear tyre R17 Abraided 160.00 140.00 1755.00 1695.00 TOTAL	10	1	Front tyre R17				
TOTAL 1755.00 1695.00 LABOUR & MISC CHARGES 1 To carry out body frame alignment 350.00 320.00 2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL 2250.00 1870.00 Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 13703.36 12217.02 2467.02	11	1	Rear alloy rim R17				
TOTAL 11453.36 10347.02 LABOUR & MISC CHARGES 1 To carry out body frame alignment 350.00 320.00 2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL 2250.00 1870.00 Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 13703.36 12217.02 2467.02	12	1	Rear tyre R17	Abraided			
LABOUR & MISC CHARGES 1 To carry out body frame alignment 350.00 320.00 2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL 2250.00 1870.00 Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 13703.36 12217.02							
1 To carry out body frame alignment 350.00 320.00 2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL 2250.00 1870.00 Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 13703.36 12217.02			TOTAL		11453.36	10347.02	
2 To remove/replace damaged parts & components. 700.00 650.00 3 To respray replaced & affected parts. 1200.00 900.00 TOTAL 2250.00 1870.00 Total Parts and Labour Cost of Repair Less (Lumpsum repair adjustment) 13703.36 12217.02 Less (Lumpsum repair adjustment) 2467.02			LABOUR & MISC CHARGES				
To respray replaced & affected parts. 1200.00 900.00 TOTAL 2250.00 1870.00 Total Parts and Labour Cost of Repair 13703.36 12217.02 Less (Lumpsum repair adjustment) 2467.02	1		To carry out body frame alignment		350.00	320.00	
TOTAL 2250.00 1870.00 Total Parts and Labour Cost of Repair 13703.36 12217.02 Less (Lumpsum repair adjustment) 2467.02	2		To remove/replace damaged parts & components	S.	700.00	650.00	
Total Parts and Labour Cost of Repair 13703.36 12217.02 Less (Lumpsum repair adjustment) 2467.02	3		To respray replaced & affected parts.		1200.00	900.00	
Less (Lumpsum repair adjustment) 2467.02			TOTAL		2250.00	1870.00	
Less (Lumpsum repair adjustment) 2467.02			Total Parts and Labour Cost of Dansin		13703 26	12217 02	
Adjustment Parts and Labour Cost of Repair 9750.00			_		15705.50		
			Adjustment Parts and Labour Cost of Re	pair		9750.00	

































