

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA23002744/UQY3Q2**Date:** 25/04/2023REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP321362
Claimant Vehicle No :	GBH9255G	Insured Vehicle No :	SNC7072P
Date of Loss:	24/02/2023	Nature of Claim:	TP
		Claim No:	MPC04024

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH9255G	Engine No:	1KD2830813
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Chassis No:	JTFAT35YX0K211794
Reg. Date:	01/11/2018 (Man. Year: 2018)	Odometer:	199948 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Habilead 6/6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Habilead 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,300.60	1,684.15	2,616.45	60.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,210.00	590.00	32.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,100.60	2,894.15	3,206.45	52.56
Approved Total (Overridden) (S\$)		2,300.00		
(S\$)	6,100.60	2,300.00	3,800.60	62.30
+ GST 8.00/8.00% (S\$)	488.05	184.00	304.05	62.30
Nett Amount (S\$)	6,588.65	2,484.00	4,104.65	62.30

INSPECTION

Date of Assignment:	16/03/2023	
Date Inspected:	17/04/2023	Inspected At: Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 24 Apr 2023)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH9255G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented / Bent	1,237.20 FL	*1,237.20 FL
2	1		*REAR TAILGATE HINGE -RH	Not Necessary	78.20 FL	*- FL
3	1		*REAR TAILGATE HINGE LOCK -RH	Bent	35.40 FL	*35.40 FL
4	1		*REAR TAILGATE STOPPER -RH	Not fitted	48.60 FL	*- FL
5	1		*REAR TAILGATE EMBLEM (TOYOTA)	Necessary	148.20 FL	*148.20 FL
6	1		*REAR TAILGATE EMBLEM (DYNA)	Necessary	18.20 FL	*18.20 FL
7	1		*REAR TAILGATE STOPPER BRACKET -RH	Bent	70.10 FL	*70.10 FL
8	1		*REAR TAILGATE LOWER MEMBER	Repair	495.60 FL	*- FL
9	1		*REAR TAILLAMP (O/S)	Cracked	296.90 FL	*296.90 FL
10	1		*REAR TAILLAMP BRACKET (O/S)	Bent	146.20 FL	*146.20 FL
11	1		*RH SIDE GATE	Repair	2,346.20 FL	*- FL
12	1		*REAR TAILGATE STICKET 70KM/H	Necessary	15.00 FS	*10.00 FS
13	1		*REAR TAILGATE STICKER 13 PAX	Necessary	15.00 FS	*10.00 FS
14	1		*RH SIDE STICKER	Not Necessary	280.00 FS	*- FS
15	1		*SET REAR SENSOR	Malfunction	300.00 FS	*200.00 FS
					Sub Total (\$\$)	
					5,530.80	2,172.20
					- List Item Discount on L Items 25.00/25.00% (\$\$)	
					1,230.20	488.05
					Total Parts (\$\$)	
					4,300.60	1,684.15

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING WORK	New	920.00	600.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	30.00
4	TO REMOVE & REPLACE REAR SENSOR	New	80.00	40.00
5	TO SPRAY PAINTING	New	680.00	520.00
Gross Labour Cost (\$)			1,800.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >