



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23002747/Uvy3e2 Date: 22/03/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SBS 6494U	Veh. Inspected	YN 1868L
Policy No.	D-22099843MFBP	Coverage (\$)	0.00
Claim No.	D23000605MFBP	Excess (\$)	0.00
Assign From	CAROLINE CABRERA	Assign Date	16/03/2023
2. Vehicle Particulars & Condition			
Make & Model	mitsubishi FM65 (M)	c.c	7545
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	FM65FMA00128	Colour	WHITE
Odometer	436415 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	KPATOS	6 mm
L/H Front Tyre	295/80 R22.5	KPATOS	6 mm
R/H Rear Tyre	295/80 R22.5 (D)	AUSTONE	6/6 mm
L/H Rear Tyre	295/80 R22.5 (D)	AUSTONE	6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/02/2023	Inspection Date	16/03/2023
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	