

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23002753/UWP3Q2**Date:** 23/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00140882203
<b>Claimant Vehicle No :</b>	YQ1624H	<b>Insured Vehicle No :</b>	GBG8530Z
Date of Loss:	28/11/2022	Nature of Claim:	TP
		Claim No:	SNM23D201998/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>YQ1624H</b>	Engine No:	4JJ14D4047
Make & Model:	ISUZU NMR85UH5A, 3.0 D (M)	Chassis No:	JAANMR85HK7102119
Reg. Date:	23/10/2019 (Man. Year: 2019)	Odometer:	94187 km
Colour:	White		
Engine Capacity:	2999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/85 R16	Rear Tyre Size:	195/85 R16 (D)
Front Left Side:	Giti 6 mm	Rear Left Side:	Giti 6/6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Giti 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,652.50	20.00	1,632.50	98.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	650.00	350.00	35.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,652.50</b>	<b>670.00</b>	<b>1,982.50</b>	<b>74.74</b>
<b>+ GST 8.00/8.00% (S\$)</b>	212.20	53.60	158.60	74.74
<b>Nett Amount (S\$)</b>	<b>2,864.70</b>	<b>723.60</b>	<b>2,141.10</b>	<b>74.74</b>

**INSPECTION**

Date of Assignment:	16/03/2023		
Date Inspected:	17/03/2023	Inspected At:	ETHOZ Protect Pte Ltd (Tampines) 22 Tampines St 92 Singapore 528876
Estimated Period of Repair:	2.0 days		

**Adjuster:** MARCUS CHUA**Manager:** XinYu

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 23 May 2023)	
Parts:	N/A	ISUZU NMR85UH5A 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ1624H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	1,450.00 FL	*- FL
2	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
3	1		*ALUMINIUM CHECKER PLATE	Serviceable	400.00 FS	*- FS
4	1		*60KM/H STICKER	Necessary	10.00 FS	*10.00 FS
5	1		*23 PAX STICKER	Necessary	10.00 FS	*10.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (\$\$)					1,870.00	20.00
- List Item Discount on L Items 15.00/15.00% (\$\$)					217.50	0.00
Total Parts (\$\$)					1,652.50	20.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO FACILITATE REPAIR	New	500.00	400.00
2	TO RESPRAY AFFECTED AREA	New	500.00	250.00
<b>Gross Labour Cost (S\$)</b>			<b>1,000.00</b>	<b>650.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >