

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123002757/AWY3Q2**Date:** 24/05/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SND6763E **Insured Vehicle No :** YN5969C

Date of Loss: 11/03/2023 Nature of Claim: TP Claim No: CDMCG23000628

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SND6763E**

Make & Model: ADIVA AD1 200, 190cc 3W Engine No: 42495778B38A15A

Reg. Date: 02/12/2019 (Man. Year: 2019) Chassis No: WBA6V120205P19541

Colour: Black Odometer: 55768 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,802.10	7,142.70	3,659.40	33.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,670.00	1,720.00	1,950.00	53.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,472.10	8,862.70	5,609.40	38.76
Approved Total (Overridden) (S\$)		7,100.00		
Nett Amount (S\$)	14,472.10	7,100.00	7,372.10	50.94

INSPECTION

Date of Assignment: 16/03/2023

Date Inspected: 03/04/2023 Inspected At: AUTO UNITED SG PTE LTD (HQ)
13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE
Singapore 417807

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 23 May 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND6763E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,320.00 FL	*1,320.00 FL
2	1		*REAR BUMPER SIDE HOLDER RH	Damaged	105.00 FL	*105.00 FL
3	1		*REAR BUMPER REFLECTOR RH	Not Necessary	76.00 FL	*- FL
4	1		*TAILLAMP RH	Cracked	525.00 FL	*525.00 FL
5	1		*REAR RH FENDER	Dented	1,949.00 FL	*1,949.00 FL
6	1		*REAR RH FENDER INNER SHIELD	Torn	2,459.00 FL	*245.90 FL
7	1		*REAR RH FENDER GLASS C/W MOULDING	Necessary	498.00 FL	*68.00 FL
8	1		*REAR RH WHEEL RIM	Cut	1,092.50 FS	*750.00 FS
9	1		*REAR RH LOWER ARM	Bent	490.00 FL	*490.00 FL
10	1		*REAR RH SHOCK ABSORBER	Not Necessary	425.00 FL	*- FL
11	1		*REAR RH KNUCKLE ARM	Damaged	892.00 FL	*892.00 FL
12	1		*REAR RH WHEEL HUB C/W BEARING	Damaged	417.00 FL	*417.00 FL
13	1		*REAR RH CONTROL ARM	Bent	302.00 FL	*302.00 FL
14	1		*REAR RH STAY ARM	Bent	310.00 FL	*310.00 FL
15	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
16	1		*REAR RH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
17	1		*REAR RH FENDER GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
18	1		*REAR RH TYRE	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,290.50	7,473.90
- List Item Discount on L Items 5.00/5.00% (S\$)	488.40	331.20
Total Parts (S\$)	10,802.10	7,142.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	600.00
2	SPRAY PAINTING	New	1,000.00	400.00
3	WIRING	New	100.00	30.00
4	TO APPLY TUFF COAT	New	150.00	60.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE REAR FENDER GLASS	New	120.00	60.00
7	TO REMOVE UPHOLSTERY	New	150.00	60.00
8	TO REMOVE REAR UNDERCARRIAGE	New	350.00	200.00
9	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
10	TO REMOVE FUEL TANK	New	150.00	80.00
11	TO PERFORM DIAGNOSTIC TEST	New	200.00	100.00
Gross Labour Cost (S\$)			3,670.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >