

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB23002767/SPA3Q2**Date:** 20/07/2023**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447_02
Claimant Vehicle No :	SJH7953T	Insured Vehicle No :	SLM1597C
Date of Loss:	10/03/2023	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH7953T	Engine No:	1NZX790225
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305076105
Reg. Date:	25/08/2008 (Man. Year: 2008)	Odometer:	275540 km
Colour:	Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45 R16	Rear Tyre Size:	205/45 R16
Front Left Side:	Tourador 5 mm	Rear Left Side:	Tourador 5 mm
Front Right Side:	Tourador 5 mm	Rear Right Side:	Tourador 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,269.80	740.25	1,529.55	67.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	488.00	440.00	48.00	9.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,757.80	1,180.25	1,577.55	57.20
Approved Total (Overridden) (\$\$)		950.00		
Nett Amount (\$\$)	2,757.80	950.00	1,807.80	65.55
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	16/03/2023		
Date Inspected:	17/03/2023	Inspected At:	Dickson Auto Care Centre Pte Ltd (HQ) 29 Ubi Road 4, Dickson Auto Centre Singapore 408619
Estimated Period of Repair:	3.0 days		

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jul 2023)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH7953T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NO PLATE WITH CASING	Cracked	45.00 F	*45.00 FL
2	1		*FRONT BUMPER	Cracked	485.00 F	*485.00 FL
3	10		*FRONT BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
4	2		*FRONT BUMPER SIDE RETAINER LH & RH	Broken	124.00 F	*124.00 FL
5	1		*FRONT BUMPER LOGO	Necessary	48.00 F	*48.00 FL
6	1		*FRONT BUMPER UPPER GRILLE	Cracked	255.00 F	*255.00 FL
7	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	79.60 F	*- FL
8	2		*FRONT BUMPER FOG LAMP LH & RH	Not Necessary	600.20 F	*- FL
9	2		*FRONT BUMPER FOG LAMP COVER LH &RH	Not Necessary	190.00 F	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	393.00 F	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	2,269.80 987.00
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 246.75
					Total Parts (\$\$)	2,269.80 740.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT FRONT HEAD LAMPS ,FOG LAMPS & TEST FOR PROEPR FUNCTIONING	New	88.00	40.00
2	TO PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGEGED PARTS & PANELS CUT & WELD IF NECESSARY AND REALIGN	New	200.00	200.00
3	TO PROVIDE SKILL LABOUR & MATERIAL TO PAINT NEW PARTS & PANEL	New	200.00	200.00
Gross Labour Cost (\$\$)			488.00	440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >