



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 3587G

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|-------------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | FRONT BRAKE DISC | NOT NECESSARY | 180.00 | - |
| 2 | SIDE MIRRORS | O/S SCRATCHED | 240.00 | 60.00 |
| 1 | HANDLE BAR | DENTED | 180.00 | 120.00 |
| 1 | SET HANDLE BAR BALANCER } | SCRATCHED | 80.00 | 60.00 |
| 1 | SET HAND GRIP } | | 80.00 | - |
| 1 | BRAKE LEVER | SCRATCHED | 58.00 | 45.00 |
| 1 | FRONT SIGNAL | SCRATCHED | 95.00 | 45.00 |
| 1 | O/S FOOTSTEP PANEL | CRACKED | 165.00 | 120.00 |
| 1 | EXHAUST PIPE ASSY | NOT NECESSARY | 780.00 | - |
| 1 | EXHAUST PROTECTOR | SCRATCHED | 88.00 | 60.00 |
| 2 | REAR SIGNALS | SCRATCHED / BROKEN | 150.00 | 50.00 |
| 1 | REAR FENDER | SCRATCHED / BROKEN | 155.00 | 90.00 |
| 1 | REAR O/S FOOTREST | SCRATCHED | 85.00 | 55.00 |
| 1 | REAR FENDER REFLECTOR | NOT NECESSARY | 48.00 | - |
| 1 | REAR SPORT RIM | TO REPAIR SEE LABOUR | 650.00 | - |
| 1 | REAR RIM BRACKET | NOT NECESSARY | 322.00 | - |
| 1 | SET FAIRING COVER | SCRATCHED | 1,350.00 | 300.00 |
| | LESS 10% DISCOUNT | | -470.60 | -100.50 |
| | | | 4,235.40 | 904.50 |
| 1 | O/S SIDE FORK TUBE ASSY (SN) (LOCAL REPAIR) | DENTED | 980.00 | 80.00 |
| 1 | SET REAR SHOCK ABSORBER (SN) (LOCAL REPAIR) | DENTED | 800.00 | 60.00 |
| | LESS 10% DISCOUNT | | -178.00 | - |
| | | | 1,602.00 | 140.00 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | FRONT FENDER - CARBON (SN) | SCRATCHED | 250.00 | 200.00 |
| 1 | SET NUMBER PLATE (SN) | DENTED | 28.00 | 28.00 |
| 1 | FORK OIL (SN) | NECESSARY | 15.00 | 15.00 |

Report Ref No. CS3/CTI22011845/Sqp3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--------------------|---|---------------|---------------------------|-------------------|
| 1 | FORK OIL SEAL (SN) | NECESSARY | 28.00 | 28.00 |
| 1 | SET STEERING CONE (SN) | NOT NECESSARY | 120.00 | - |
| 1 | AIR FILTER BOX COVER - CARBON (SN) | NOT NECESSARY | 450.00 | - |
| 1 | FOOTSTEP SIDE STOPPER (SN) | NOT NECESSARY | 48.00 | - |
| | | | 939.00 | 271.00 |
| | LABOUR | | | |
| | TO PROVIDE TOWING SERVICE. | | 50.00 | 30.00 |
| | TO CHECK ELECTRICAL SYSTEM, WIRE HARNESS AND FOCUS HEADLAMP. | | 80.00 | 30.00 |
| | TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR SPORT RIM. | | 480.00 | 280.00 |
| | | | 610.00 | 340.00 |
| GRAND TOTAL | | | 7,386.40 | 1,655.50 |

| | | | |
|---|--|--|-----------------|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 1,300.00 |
|---|--|--|-----------------|

Report Ref No. CS3/CTI22011845/Sqp3e2-1

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.