



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 3587G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BRAKE DISC	NOT NECESSARY	180.00	-
2	SIDE MIRRORS	O/S SCRATCHED	240.00	60.00
1	HANDLE BAR	DENTED	180.00	120.00
1	SET HANDLE BAR BALANCER }	SCRATCHED	80.00	60.00
1	SET HAND GRIP }		80.00	-
1	BRAKE LEVER	SCRATCHED	58.00	45.00
1	FRONT SIGNAL	SCRATCHED	95.00	45.00
1	O/S FOOTSTEP PANEL	CRACKED	165.00	120.00
1	EXHAUST PIPE ASSY	NOT NECESSARY	780.00	-
1	EXHAUST PROTECTOR	SCRATCHED	88.00	60.00
2	REAR SIGNALS	SCRATCHED / BROKEN	150.00	50.00
1	REAR FENDER	SCRATCHED / BROKEN	155.00	90.00
1	REAR O/S FOOTREST	SCRATCHED	85.00	55.00
1	REAR FENDER REFLECTOR	NOT NECESSARY	48.00	-
1	REAR SPORT RIM	TO REPAIR SEE LABOUR	650.00	-
1	REAR RIM BRACKET	NOT NECESSARY	322.00	-
1	SET FAIRING COVER	SCRATCHED	1,350.00	300.00
	LESS 10% DISCOUNT		-470.60	-100.50
			4,235.40	904.50
1	O/S SIDE FORK TUBE ASSY (SN) (LOCAL REPAIR)	DENTED	980.00	80.00
1	SET REAR SHOCK ABSORBER (SN) (LOCAL REPAIR)	DENTED	800.00	60.00
	LESS 10% DISCOUNT		-178.00	-
			1,602.00	140.00
<u>SPECIAL NETT ITEMS</u>				
1	FRONT FENDER - CARBON (SN)	SCRATCHED	250.00	200.00
1	SET NUMBER PLATE (SN)	DENTED	28.00	28.00
1	FORK OIL (SN)	NECESSARY	15.00	15.00

Report Ref No. CS3/CTI22011845/Sqp3e2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FORK OIL SEAL (SN)	NECESSARY	28.00	28.00
1	SET STEERING CONE (SN)	NOT NECESSARY	120.00	-
1	AIR FILTER BOX COVER - CARBON (SN)	NOT NECESSARY	450.00	-
1	FOOTSTEP SIDE STOPPER (SN)	NOT NECESSARY	48.00	-
			939.00	271.00
	LABOUR			
	TO PROVIDE TOWING SERVICE.		50.00	30.00
	TO CHECK ELECTRICAL SYSTEM, WIRE HARNESS AND FOCUS HEADLAMP.		80.00	30.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR SPORT RIM.		480.00	280.00
			610.00	340.00
GRAND TOTAL			7,386.40	1,655.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,300.00

Report Ref No. CS3/CTI22011845/Sqp3e2-1

S MOHAMED IRFAN BIN MOHAMED IQBAL

Asst. Automotive Assessor

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.