

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGN 9229S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER FOR BUMPER PRIMED (SN)	DEFORMED	1,452.18	1,452.18
1	SENSOR BRACKET (SN)	NECESSARY	15.49	15.49
1	SENSOR BRACKET (SN)	NECESSARY	15.49	15.49
2	SENSOR BRACKET @\$14.85 (SN)	NECESSARY	29.70	29.70
1	SEAL RING SATIN BLACK (SN)	NECESSARY	1.53	1.53
1	SENSOR PRIMED (SN)	NOT WORKING	194.63	194.63
1	2K-PLASTIC ADHESIVE (SN)	NECESSARY	84.64	84.64
1	BONDING AGENT FOR PLASTIC (SN)	NECESSARY	74.37	74.37
1	FOAM INSERT (SN)	NOT NECESSARY	73.70	-
1	IMPACT BEAM REINFORCEMENT (SN)	NOT NECESSARY	835.24	-
1	GUIDE PIECE BUMPER SIDE BRACKET LH (SN)	NOT NECESSARY	37.13	-
1	GUIDE PIECE BUMPER SIDE BRACKET RH (SN)	NOT NECESSARY	37.13	-
1	GUIDE BUMPER CTR BRACKET (SN)	NOT NECESSARY	85.41	-
1	RADIATOR GRILLE SATIN BLA (SN)	NOT NECESSARY	528.92	-
1	VW SIGN BLACK/BRIGHT CHRO (SN)	SCRATCHED	106.72	106.72
1	COOLING AIR GRILL SATIN B BUMPER CTR BRACKET (SN)	NOT NECESSARY	277.89	-
1	FRT NUMBER PLATE (SN)	BENT	80.00	80.00
			3,930.17	2,054.75
	<u>LABOUR</u>			
	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR.		280.00	280.00
	B&P DIAGNOSIS AND PROGRAMMING.		480.00	480.00
	LABOUR.		2,520.00	840.00
	SPRAY PAINT.		2,400.00	800.00
			5,680.00	2,400.00
	GRAND TOTAL		9,610.17	4,454.75



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 4,454.75

Report Ref No. CS/FCI23002782/Rvy3m4

MKB

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

X.S.

**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

**Licensed Appraiser**