

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 162X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	BENT	1,536.00	1,536.00
1	FRONT BONNET INNER LOCK	NOT NECESSARY	250.00	-
1	FRONT GRILLE ASSY	CRACKED	840.00	840.00
1	FRONT TOP PANEL	TO REPAIR SEE LABOUR	450.00	-
1	FRONT BUMPER	DEFORMED	1,280.00	1,280.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	352.00	-
1	FRONT BUMPER INNER SPONGE	CRACKED	160.00	160.00
1	FRONT BUMPER CLIPS & RIVETS	NECESSARY	150.00	120.00
2	FRONT BUMPER SIDE RETAINERS @\$30.00	NOT NECESSARY	60.00	-
2	FRONT HEAD LAMPS @\$2,500.00	N/S CRACKED	5,000.00	2,500.00
1	FRONT NUMBER PLATE BASE	DEFORMED	128.00	128.00
1	R/H FRONT WHEEL GARNISH	NOT NECESSARY	170.00	-
2	FRONT BONNET AIR PUSH DAMPERS WITH IMPACT SENSORS @\$410.00	SHORTED	820.00	820.00
2	FRONT BONNET SPRING LOCKS @\$35.00 (ADDITIONAL)	JAMMED	70.00	70.00
1	FRONT SPEED/LANE RADAR SENSOR (ADDITIONAL)	SHORTED	992.00	992.00
	LESS 10% DISCOUNT		-	-844.60
			12,258.00	7,601.40
	<u>LABOUR</u>			
	LABOUR CHARGE TO STRAIGHTEN FRONT BODY PANEL, REMOVE & REPLACE THE ABOVE LISTED DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT TOP PANEL.		1,500.00	1,000.00
	LABOUR CHARGE TO RECONNECT FRONT LAMP WIRE HARDNESS & REFOCUS HEAD LIGHT.		60.00	40.00
	LABOUR CHARGE TO CALIBRATE & REPROGRAMMING INFO SYSTEM.		400.00	250.00
	LABOUR CHARGE TO PUTTY AND RESPRAY PAINTING ON THE AFFECTED PARTS & AREAS.		1,200.00	800.00
	TOWING FEES (ADDITIONAL).		120.00	120.00
			3,280.00	2,210.00
	GRAND TOTAL		15,538.00	9,811.40

Report Ref No. CS/GAI23002785/Rny3m4



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 9,811.40

Report Ref No. CS/GAI23002785/Rny3m4

MKB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser