

ASS. REC. BY:

REF:

AG2/ 23002791/kw

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WYS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 days

Res.: Yes or No

Lum Sum:

I.B.I. %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMJ 1223K

Yr Regn:

01, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Mer A200

c.c

1332

Colour

m. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

39273

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD17708725020108

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

R:

225/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

15/3/23

D.O.I.

20/3/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/ GIA & ESI not ready

14/4 11 Rm @ 2000 Calm

Date/Time, File Pass to?



: Prel. Report



: Final Report

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation

S - RS. SI

Parking

Others

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$)

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: MERCEDES BENZ A200

Engine/Chassis No.: WDD1770872J020108


Date of accident: 15.03.23

Damaged area: Rear

Date: 24/03/2023

Claim Type: TP

VRN: SMJ1223K



Not Not hatched
1/1/2023 & 2000h
Recovery After Repair
2 days

List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Rear bumper <i>1337 Hua</i>	1	\$ 1,417.00	\$	1,417.00 ✓
2	Rear bumper reinforcement <i>11</i>	1	\$ 983.00	\$	983.00 X
3	Rear bumper side retainer <i>2</i>	2	\$ 163.00	\$	326.00 X
4	Rear bumper tow cover <i>1</i>	1	\$ 109.00	\$	109.00 X
5	Rear bumper lower <i>322.45 mhm</i>	1	\$ 661.00	\$	661.00 ✓
6	Rear bumper lower center chrome moulding <i>278.90 2nd</i>	1	\$ 455.00	\$	455.00 ✓
7	Rear bumper lower side chrome moulding <i>2 SP 2</i>	2	\$ 263.00	\$	526.00 X
8	Rear bumper inner bracket upper <i>1</i>	1	\$ 269.00	\$	269.00 X
9	Rear bumper inner bracket lower <i>1</i>	1	\$ 254.00	\$	254.00 X
Subtotal				\$	5,000.00
List discount				10.00%	
Total				\$	4,500.00

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper reverse sensor <i>21</i>	21	\$ 180.00	\$ 360.00 ✓
2	Rear bumper sensor holder <i>2</i>	2	\$ 28.00	\$ 56.00 ✓
3	Rear bumper clips <i>12</i>	12	\$ 5.50	\$ 66.00 ✓
4	Sundries <i>1</i>	1	\$ 50.00	\$ 50.00 ✓
Total				\$ 532.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00 <i>2501</i>
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00 <i>151</i>
3	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00 <i>2501</i>
4	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,350.00
Estimate Grand Total			\$ 7,382.00