

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123002792/SNY3E2**Date:** 02/08/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBD271P**Insured Vehicle No :** GBK3403U

Date of Loss: 15/03/2023

Nature of Claim:

TP

Claim No: CDMCG23000654

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBD271P**Make & Model: NISSAN NV200, 1.5 L ABS AIRBAG 2WD 6DR
EURO 5 (M)

Engine No: K9KC400D053546

Reg. Date: 05/05/2014 (Man. Year: 2014)

Chassis No: VSKYBAM20Z0079087

Colour: Grey

Odometer: 244461 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size:

195 R15C

Front Left Side: Bridgestone 5 mm

Rear Left Side:

Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side:

Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,267.50	6,562.96	7,704.54	54.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,220.00	1,980.00	3,240.00	62.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,487.50	8,542.96	10,944.54	56.16
Approved Total (Overridden) (S\$)		6,850.00		
(S\$)	19,487.50	6,850.00	12,637.50	64.85
+ GST 8.00/8.00% (S\$)	1,559.00	548.00	1,011.00	64.85
Nett Amount (S\$)	21,046.50	7,398.00	13,648.50	64.85

INSPECTION

Date of Assignment: 17/03/2023

Date Inspected:

17/03/2023

Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair:

5.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Aug 2023)	
Parts:	N/A	NISSAN NV200 1.5 L ABS AIRBAG 2WD 6DR EURO 5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD271P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH SLIDING DOOR	Repair	1,281.70 FL	*- FL
2	1		*LH SLIDING DOOR CENTRE RAILING	Not Necessary	298.80 FL	*- FL
3	1		*LH SLIDING DOOR CENTRE RAILING SIDE COVER	Not Necessary	59.00 FL	*- FL
4	1		*LH REAR SIDE PANEL	Dented	1,636.10 FL	*1,636.10 FL
5	1		*LH REAR SIDE PANEL AIR VENT	Broken	79.20 FL	*79.20 FL
6	1		*LH REAR SIDE PANEL SPLASH SHIELD	Not Necessary	162.00 FL	*- FL
7	1		*SET LH REAR SIDE PANEL SPLASH SHIELD CLIPS	Not Necessary	80.00 FL	*- FL
8	1		*LH REAR SIDE PANEL INNER TRIM COVER	Broken	256.00 FL	*256.00 FL
9	1		*SET LH REAR SIDE PANEL INNER TRIM COVER CLIPS	Necessary	60.00 FL	*20.00 FL
10	1		*REAR BUMPER	Broken	624.80 FL	*624.80 FL
11	1		*REAR BUMPER LH REFLECTOR	Broken	58.70 FL	*58.70 FL
12	1		*REAR BUMPER LH RETAINER	Cracked	37.70 FL	*37.70 FL
13	1		*REAR BUMPER RH RETAINER	Not Necessary	37.70 FL	*- FL
14	1		*REAR BUMPER INNER SPONGE	Cracked	88.30 FL	*88.30 FL
15	1		*TAILGATE LH	Buckled	1,409.80 FL	*1,409.80 FL
16	2		*TAILGATE LH OUTER MOULDING	Cracked	336.80 FL	*336.80 FL
17	1		*TAILGATE LH NUMBER PLATE LAMPS	Not Necessary	269.90 FL	*- FL
18	1		*TAILGATE LH CENTRE EMBLEM	Necessary	62.30 FL	*62.30 FL
19	1		*TAILGATE LH NV200 EMBLEM	Necessary	87.90 FL	*87.90 FL
20	1		*TAILGATE LH WINDSCREEN GLASS	Not Necessary	838.00 FL	*- FL
21	1		*TAILGATE LH DOOR WIPER MOTOR	Not Necessary	457.80 FL	*- FL
22	1		*TAILGATE LH UPPER HINGE	Not Necessary	99.10 FL	*- FL
23	1		*TAILGATE LH LOWER HINGE	Not Necessary	99.10 FL	*- FL
24	1		*TAILGATE LH CHECKER	Not Necessary	44.60 FL	*- FL
25	1		*TAILGATE LH CENTRAL LOCKING ASSY	Dented	338.70 FL	*289.00 FL
26	1		*TAILGATE LH INNER TRIM BOARD	Cut	389.50 FL	*213.00 FL
27	1		*SET TAILGATE LH INNER TRIM BOARD CLIPS	Necessary	80.00 FL	*20.00 FL
28	1		*TAILGATE LH UPPER LOCK	Dented	88.90 FL	*88.90 FL
29	1		*TAILGATE LH LOWER LOCK	Dented	124.30 FL	*124.30 FL
30	1		*TAILGATE RH	Not Necessary	1,056.70 FL	*- FL
31	1		*TAILGATE RH EMBLEM	Necessary	108.70 FL	*66.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
32	1		*TAILGATE RH UPPER HINGE	Not Necessary	99.10 FL	*- FL
33	1		*TAILGATE RH LOWER HINGE	Not Necessary	99.10 FL	*- FL
34	1		*TAILGATE RH CHECKER	Not Necessary	44.60 FL	*- FL
35	1		*TAILGATE RH INNER TRIM BOARD	Not Necessary	203.80 FL	*- FL
36	1		*SET TAILGATE RH INNER TRIM BOARD CLIPS	Not Necessary	80.00 FL	*- FL
37	1		*TAILGATE RH UPPER LOCK	Not Necessary	118.70 FL	*- FL
38	1		*TAILGATE RH LOWER LOCK	Not Necessary	98.30 FL	*- FL
39	1		*TAILGATE RH CENTRE BRACKET	Not Necessary	98.30 FL	*- FL
40	1		*TAILGATE RH DOOR VERTICAL RUBBER SEAL	Not Necessary	114.50 FL	*- FL
41	1		*REAR DOOR WEATHERSTRIP	Cut	176.80 FL	*176.80 FL
42	1		*END PANEL (OUTER)	Dented	544.70 FL	*544.70 FL
43	1		*END PANEL (INNER)	Buckled	218.90 FL	*218.90 FL
44	1		*END PANEL INNER GARNISH	Not Necessary	84.30 FL	*- FL
45	1		*SET END PANEL INNER GARNISH CLIPS	Not Necessary	80.00 FL	*- FL
46	1		*SPARE TYRE CARRIAGE	Not Necessary	281.10 FL	*- FL
47	1		*SPARE TYRE CARRIAGE BRACKET	Not Necessary	125.60 FL	*- FL
48	1		*LH TAILLAMP ASSY	Cracked	342.60 FL	*272.00 FL
49	1		*LH TAILLAMP PANEL	Dented	103.20 FL	*103.20 FL
50	1		*LH TAILLAMP SPONGE GASKET	Not Necessary	36.00 FL	*- FL
51	1		*RH TAILLAMP ASSY	Not Necessary	342.60 FL	*- FL
52	1		*RH TAILLAMP PANEL	Not Necessary	103.20 FL	*- FL
53	1		*RH TAILLAMP SPONGE GASKET	Not Necessary	36.00 FL	*- FL
54	1		*EXHAUST SILENCER	Not Necessary	596.50 FL	*- FL
55	1		*EXHAUST SILENCER GASKET	Not Necessary	55.00 FL	*- FL
56	1		*TAILGATE RH WINDSCREEN GLASS SEALANT (RH TAILGATE REPAIR)	Not Necessary	80.00 FS	*- FS
57	1		*TAILGATE RH WINDSCREEN GLASS INNER SEAL (RH TAILGATE REPAIR)	Not Necessary	60.00 FS	*- FS
58	1		*TAILGATE RH 5PAX STICKER	Necessary	28.00 FS	*20.00 FS
59	1		*TAILGATE LH WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
60	1		*TAILGATE LH WINDSCREEN GLASS INNER SEAL	Necessary	60.00 FS	*30.00 FS
61	1		*TAILGATE LH 70KM/H STICKER	Necessary	28.00 FS	*20.00 FS
62	1		*SET END PANEL (OUTER) JOINT SEALANT	Necessary	80.00 FS	*40.00 FS
63	1		*END PANEL (INNER) JOINT SEALANT	Not Necessary	80.00 FS	*- FS
64	1		*LH REAR SIDE PANEL JOINT SEALANT	Necessary	80.00 FS	*40.00 FS
65	1		*SET REAR BUMPER REVERSE SENSOR	Faulty	350.00 FS	*200.00 FS
66	1		*REAR NUMBER PLATE	Cut	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (\$)	15,741.00	7,244.40
				- List Item Discount on L Items 10.00/10.00% (\$)	1,473.50	681.44
				Total Parts (\$)	14,267.50	6,562.96
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	2,000.00	800.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,800.00	800.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	150.00	60.00
5	REMOVE AND REPLACE LH SLIDING DOOR INNER MECHANISM TO NEW DOOR	New	150.00	0.00
6	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	80.00	30.00
7	REMOVE AND REPLACE REAR INNER TRIMS AND BOARDS TO ASSIST REPAIR	New	380.00	60.00
8	REMOVE AND REINSTALL TAILGATE LH WINDSCREEN GLASS TO ASSIST REPAIR	New	200.00	80.00
9	REMOVE AND REINSTALL TAILGATE RH WINDSCREEN GLASS TO ASSIST REPAIR	New	200.00	80.00
10	REMOVE AND REPLACE TAILGATE LH INNER MECHANISM TO NEW DOOR	New	180.00	40.00
Gross Labour Cost (\$)			5,220.00	1,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >