

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002797/SVP3Q2**Date:** 11/07/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00040482200

Claimant Vehicle No : SFK5588J **Insured Vehicle No :** GBB164B

Date of Loss: 16/03/2023 Nature of Claim: TP Claim No: SNM23D202000/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFK5588J**

Make & Model: VOLKSWAGEN GOLF, 2.0 GTI (A) Engine No: BWA213591

Reg. Date: 11/12/2008 (Man. Year: 2008) Chassis No: WVVZZZ1KZ8U026187

Colour: Yellow/Black Odometer: 213365 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18 Rear Tyre Size: 225/40Z R18

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,414.00	3,808.90	15,605.10	80.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,150.00	630.00	2,520.00	80.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,564.00	4,438.90	18,125.10	80.33
Approved Total (Overridden) (S\$)		3,550.00		
(S\$)	22,564.00	3,550.00	19,014.00	84.27
+ GST 8.00/8.00% (S\$)	1,805.12	284.00	1,521.12	84.27
Nett Amount (S\$)	24,369.12	3,834.00	20,535.12	84.27

INSPECTION

Date of Assignment: 17/03/2023

Date Inspected: 20/03/2023 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqubal**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2023)
Parts: 144	VOLKSWAGEN GOLF 2.0 GTI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SFK5588J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,748.00 FL	*1,215.00 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FL	*30.00 FL
3	1		*FRONT BUMPER RH FOG LAMP	Not Necessary	362.00 FL	*- FL
4	1		*FRONT BUMPER RH FOG LAMP COVER	Not Necessary	128.00 FL	*- FL
5	1		*FRONT BUMPER RH SIDE RETAINER	Not Necessary	34.00 FL	*- FL
6	1		*FRONT BUMPER LH SIDE RETAINER	Not Necessary	34.00 FL	*- FL
7	1		*FRONT BUMPER INNER SPONGE	Not Necessary	78.00 FL	*- FL
8	1		*FRONT RH FENDER SPLASH SHIELD (FRONT)	Not Necessary	156.00 FL	*- FL
9	1		*SET FRONT RH FENDER SPLASH SHIELD CLIPS (FRONT)	Not Necessary	80.00 FL	*- FL
10	1		*FRONT RH FENDER SPLASH SHIELD (REAR)	Not Necessary	142.00 FL	*- FL
11	1		*SET FRONT RH FENDER SPLASH SHIELD CLIPS (REAR)	Not Necessary	80.00 FL	*- FL
12	1		*RH HEADLAMP ASSY	Cracked	1,876.00 FL	*1,876.00 FL
13	1		*RH HEADLAMP LOWER BRACKET	Not Necessary	67.00 FL	*- FL
14	1		*SUPPORT PANEL	Not Necessary	1,123.00 FL	*- FL
15	1		*STEERING RACK AND PINION	Not Necessary	3,878.00 FL	*- FL
16	1		*FRONT RH WHEEL BEARING	Not Necessary	595.00 FL	*- FL
17	1		*FRONT RH SHOCK ABSORBER	Not Necessary	462.00 FL	*- FL
18	1		*FRONT RH KNUCKLE ARM	Not Necessary	674.00 FL	*- FL
19	1		*FRONT RH KNUCKLE ARM BALL JOINT	Not Necessary	134.00 FL	*- FL
20	1		*FRONT RH LOWER ARM	Not Necessary	389.00 FL	*- FL
21	1		*FRONT RH DRIVE SHAFT	Not Necessary	2,562.00 FL	*- FL
22	1		*FRONT RH DOOR	Not Necessary	2,026.00 FL	*- FL
23	1		*RH SIDE MIRROR ASSY	Not Necessary	1,352.00 FL	*- FL
24	1		*FRONT RH CARBON FIBRE FENDER	Scratched	1,200.00 FS	*1,000.00 FS
25	1		*BRAKE FLUID	Not Necessary	80.00 FS	*- FS
26	1		*FRONT RH SPORT RIM	Not Necessary	1,280.00 FS	*- FS
27	1		*FRONT RH TYRE	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,220.00	4,121.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,806.00	312.10
Total Parts (\$\$)	19,414.00	3,808.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS .TO PANEL BEATING,CUT /WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,200.00	400.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,000.00	200.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	80.00	0.00
5	REFOCUS AND ADJUST HEADLAMPS ASSY	New	80.00	0.00
6	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	80.00	0.00
7	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	450.00	0.00
8	REMOVE AND REINSTALL FRONT RH DOOR INNER MECHANISM TO NEW DOOR	New	180.00	0.00
Gross Labour Cost (\$\$)			3,150.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >